

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/17/2015

Document Number:

668702405

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	246341	327090	HELGELAND, GARY	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	ALL INSPECTIONS

Compliance Summary:QtrQtr: NENW Sec: 5 Twp: 4N Range: 65W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/28/2006	200101110	PR	PR	SATISFACTORY		Pass	No
09/26/2000	200010162	PR	PR	SATISFACTORY		Pass	No
03/31/1994	500170676		PR				

Inspector Comment:Interim reclamation inspection only.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
246341	WELL	PR	11/18/2008	GW	123-14138	LEE 2	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	Comment			
Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Predrill				
Location ID: 246341				
Site Preparation:				
Lease Road Adeq.:		Pads:	Soil Stockpile:	
S/A/V:				
Corrective Action:		Date:	CDP Num.:	
Form 2A COAs:				
S/A/V:		Comment:		
CA:		Date:		
Wildlife BMPs:				
S/A/V:		Comment:		
CA:		Date:		
Stormwater:				
Comment:				
Staking:				
On Site Inspection (305):				
Surface Owner Contact Information:				
Name:		Address:		
Phone Number:		Cell Phone:		
Operator Rep. Contact Information:				
Landman Name:		Phone Number:		
Date Onsite Request Received:		Date of Rule 306 Consultation:		
Request LGD Attendance:				
LGD Contact Information:				
Name:		Phone Number:	Agreed to Attend:	
Summary of Landowner Issues:				
Summary of Operator Response to Landowner Issues:				
Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:				
Facility				

Facility ID: 246341	Type: WELL	API Number: 123-14138	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: Interim reclamation inspection only.**Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? Pass CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass

Inspector Name: HELGELAND, GARY

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass

Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Pass

Recontoured Pass

Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT