

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
02/18/2015

Document Number:  
668702418

Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>245992</u>	<u>326864</u>	<u>HELGELAND, GARY</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>100322</u>
Name of Operator:	<u>NOBLE ENERGY INC</u>
Address:	<u>1625 BROADWAY STE 2200</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
PAVELKA , LINDA	303-228-4060	lpavelka@nobleenergyinc.com	REGULATORY ANALYST

**Compliance Summary:**

QtrQtr: SWNE Sec: 5 Twp: 4N Range: 65W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/16/2012	661600626	PR	PR	SATISFACTORY			No
01/03/2011	200292617	PR	PR	SATISFACTORY	I		No
11/28/2006	200101108	PR	PR	SATISFACTORY		Pass	No
03/31/1994	500170285		PR				

**Inspector Comment:**

*Interim reclamation inspection only.*

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245992	WELL	PR	06/25/1988	OW	123-13788	LEHAN 2	PR <input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/A/V): \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

**Venting:**

Yes/No	Comment
--------	---------

**Flaring:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
------	------------------------------	---------	-------------------	---------

**Predrill**

Location ID: 245992

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 245992 Type: WELL API Number: 123-13788 Status: PR Insp. Status: PR

**Producing Well**

Comment: Interim reclamation inspection only.

**Environmental**

**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

DWR Receipt Num: Owner Name: GPS: Lat Long

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):
Comment:
Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:
Land Use:
Comment:
1003a. Debris removed? Pass CM CA Date
Waste Material Onsite? Pass CM CA Date
Unused or unneeded equipment onsite? Pass CM CA Date
Pit, cellars, rat holes and other bores closed? Pass CM CA Date
Guy line anchors removed? Pass CM CA Date
Guy line anchors marked? CM CA Date
1003b. Area no longer in use? Pass Production areas stabilized? Pass

1003c. Compacted areas have been cross ripped? Pass  
 1003d. Drilling pit closed? Pass                      Subsidence over on drill pit? Pass  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass  
           Production areas have been stabilized? Pass                      Segregated soils have been replaced? Pass

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced Pass                      Recontoured Pass                      Perennial forage re-established Pass

Non-Cropland

Top soil replaced \_\_\_\_\_                      Recontoured \_\_\_\_\_                      80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? P

Comment: \_\_\_\_\_

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_                      Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_                      Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_                      No disturbance /Location never built \_\_\_\_\_

Access Roads            Regraded \_\_\_\_\_                      Contoured \_\_\_\_\_                      Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_                      Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_                      Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_                      Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_                      Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_                      Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_                      Well Release on Active Location                       Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

S/A/V: SATISFACTOR                      Corrective Date: \_\_\_\_\_  
 Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT