



photo 1: Center of the location facing north.



photo 2: Center of the location facing west.



photo 3: Center of the location facing south.



photo 4: Center of the location facing east.



photo 5: Weed growth (kochia) throughout the location.



photo 6: Cement block and plastic pipe found on location.




photo 7: Facing north, bare areas found south of the location. Lat/Long:38.42691/-103.01364



photo 8: Facing northeast, surrounding vegetation around the location.