



**photo 1:** Facing northeast towards the location.



**photo 2:** Well head remains and pipe sticks out of ground. Lat/Long: 38.42055/-103.00909



photo 3: Plastic pipe debris remains.



photo 4: Facing west towards the location. Vegetation is not 80% of surrounding vegetation.



**photo 5:** Metal barrel found at the north side of the location. Lat/Long:38.42108/-103.00899



**photo 6:** Metal pipe found at the northwest corner of the location. Lat/Long:38.42114/-103.00960



**photo 7:** Metal pipe found at the southwest corner of the location. Lat/Long:38.42065/-103.00961



**photo 8:** Facing northwest, surrounding vegetation around the location.