

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
02/18/2015

Document Number:
673502128

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>212942</u>	<u>384495</u>	<u>COSTA, RYAN</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>8005</u>
Name of Operator:	<u>BERRY ENERGY INC*WALTER</u>
Address:	<u>1717 WASHINGTON AVE</u>
City:	<u>GOLDEN</u> State: <u>CO</u> Zip: <u>80401-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Ramos, Martha		martha.ramos@state.co.us	
Dennis, Penny	303-279-0190/66190	berryenergy@comcast.net	
Cruson, Michael	(303) 279-0190	mcruson@berryenergyinc.com	All Inspections
Bidle, Holly	(303) 279-0190/ (713) 898-2637	berryenergyhreed@comcast.net	Regulatory manager

Compliance Summary:

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/05/2011	664000090	PA	PA	ACTION REQUIRED		Fail	No
12/28/2010	200290393	SR	PA	ACTION REQUIRED	F	Fail	Yes
05/12/2010	200248649	SR	PA	ACTION REQUIRED	F	Fail	Yes
01/04/2008	200125252	SR	PA	ACTION REQUIRED	F	Fail	Yes
04/12/2007	200109024	SR	PA	ACTION REQUIRED		Fail	Yes
05/04/2004	200054664	CA	PA	SATISFACTORY		Pass	No
05/03/2004	200054646	CA	PA	SATISFACTORY		Pass	No
10/07/2003	200046378	MI	AC	ACTION REQUIRED		Fail	Yes
08/27/2003	200043328	RT	AC	SATISFACTORY		Pass	No
07/25/2002	200029476	RT	AC	SATISFACTORY		Pass	No
08/10/2001	200019419	RT	AC	SATISFACTORY	I	Pass	No
08/31/2000	200009318	RT	AC	SATISFACTORY	I	Pass	No
01/12/1999	500144995	PR	AC			Pass	No
02/02/1996	500144994	PR	AC			Pass	No
11/16/1994	500144990		AC				

Inspector Comment:

RECLAMATION INSPECTION

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
212942	WELL	PA	05/04/2004	ERIW	061-06303	FRAZEE B-1	PA	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 212942

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 212942 Type: WELL API Number: 061-06303 Status: PA Insp. Status: PA

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

	Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled Pass

Debris removed Fail No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured Pass

Compaction alleviation _____ Dust and erosion control In

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present Fail Subsidence Pass

Comment: The location did not have adequate vegetation and has areas of weeds. There are bare areas with no vegetation growth 100'x100' and several more areas to the south of the location. Remnants of debris remain. SEE ATTACHED PHOTOS.

Corrective Action: Remove any debris that remains. Control weed growth. Seed bare areas to establish vegetation to 80% of surrounding/reference area. Date 05/31/2015

Overall Final Reclamation Fail Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Submit Form 4 when corrective actions are completed. Include photographs of the vegetation in four cardinal directions as well as one close up of the plant community and documenting completion of corrective actions required in this inspection. Provide method used to determine if the re-vegetation standard has been met.	CostaR	02/23/2015
Establish vegetation with total perennial non-invasive plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture that matches the adjacent pastureland or a seed mixture requested by the landowner. Continue to monitor and manage this site until Final Reclamation has Passed.	CostaR	02/23/2015

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673502129	Site Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3556161

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)