



**photo 1:** Access road towards the location.



**photo 2:** Facing north, along access road towards the location.





**photo 3:** Facing north towards the location.



**photo 4:** Oil stained soil found at the center of the location. Lat/Long: 38.42419/-103.01796





**photo 5:** Center of the location facing north



**photo 6:** Center of the location facing west.





**photo 7:** Center of the location facing south.



**photo 8:** Center of the location facing east.





**photo 9:** Areas of weed growth (Russian thistle, Kochia) found throughout the location.



**photo 10:** Facing west, surround vegetation around the location.