



photo 1: Facing south towards the location.



photo 2: Facing northwest towards the location.



photo 3: Facing north towards the location. Area with sparse weed growth and bare of vegetation.



photo 4: Facing west towards the location. Area bare of vegetation growth, 75'x50'.



photo 5: Weed growth (Russian thistle, kochia) in areas throughout the location.



photo 6: Two wooden boards left at the west side of the location.



photo 7: What appears to be an access road to the location has been revegetated.



photo 8: Facing west, surrounding vegetation around the location.