



photo 1: Facing south along the access road towards the location.



photo 2: Facing south along the access road towards the location.



photo 3: Facing southeast towards the location.



photo 4: Facing east towards the location. The location is bare of vegetation.



photo 5: Facing northeast towards the location. The location is bare of vegetation.



photo 6: Facing north towards the location. The location is bare of vegetation.



photo 7: Weeds (Russian thistle) around the well head.



photo 8: Fence around the tank battery is down and there is weeds around the perimeter.



photo 9: Guy line anchor marker is broken at the northwest corner.



photo 10: Facing east, surrounding vegetation around the location.