

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:  
02/27/2015Document Number:  
668501099Overall Inspection:  
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	213092	324844	Welsh, Brian	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 56565Name of Operator: MERIT ENERGY COMPANYAddress: 13727 NOEL ROAD STE 1200City: DALLAS State: TX Zip: 75240

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
valliquette, arlene	(972) 628-1558	arlene.valliquette@meritenergy.com	

**Compliance Summary:**QtrQtr: SWSE Sec: 22 Twp: 20S Range: 48W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/18/2014	668500713	PR	PR	ACTION REQUIRED	P		No
06/20/2013	668600953	PR	PR	SATISFACTORY			No
02/27/2012	663900665	PR	PR	ACTION REQUIRED	P		No
12/09/2010	200289102	PR	PR	SATISFACTORY			No
06/15/2010	200255962	PR	PR	SATISFACTORY			No
09/15/2008	200195659	PR	PR	SATISFACTORY			No
11/07/2007	200121529	PR	PR	SATISFACTORY			No
06/06/2007	200112802	PR	PR	ACTION REQUIRED		Fail	Yes
03/16/2000	200005222	PR	PR	SATISFACTORY	I	Pass	No
02/21/1997	500145266	PR	PR			Pass	No
12/05/1995	500145265	PR	PR			Pass	Yes
11/15/1994	500145264		PR				

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115351	PIT		09/23/1999		-	AMYX 1	<input type="checkbox"/>
213092	WELL	PR	06/27/1985	GW	061-06453	AMYX 1	PR <input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Inspector Name: Welsh, Brian

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

#### Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	TWO TRACKTHROUGH PASTUREWITH DEEP RUTSGOING TOWELLHEAD		

#### Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	LEASE SIGN AT WELLHEAD HAS BEEN UPDATED		
TANK LABELS/PLACARDS	SATISFACTORY	STICKERS ONTANKS HAVE BEEN UPDATED		
BATTERY	SATISFACTORY	LEASE SIGN AT BATTERY HAS BEEN UPDATED		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

#### Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK BATTERY	SATISFACTORY	WIRE FENCEAROUND TANKS		
WELLHEAD	SATISFACTORY	PIPE FENCEAROUND WELLHEAD		
SEPARATOR	SATISFACTORY	WIRE FENCEWHERE OLDSEPARATOR USED TO BE		

#### Venting:

Yes/No	Comment
NO	

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 213092

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** SATISFACTORY **Comment:** NO COA'S**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 213092 Type: WELL API Number: 061-06453 Status: PR Insp. Status: PR

**Producing Well**

Comment: PRODUCING

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: Welsh, Brian

Comment:

Corrective Action:

Date:

Reportable:

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

**Water Well:**

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started:

Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA

CA Date

Waste Material Onsite? Pass CM

CA

CA Date

Unused or unneeded equipment onsite? Pass CM

CA

CA Date

Pit, cellars, rat holes and other bores closed? Pass CM

CA

CA Date

Guy line anchors removed? CM

CA

CA Date

Guy line anchors marked? CM

CA

CA Date

1003b. Area no longer in use?

Production areas stabilized ?

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed?

Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized?

Segregated soils have been replaced?

**RESTORATION AND REVEGETATION**

**Cropland**

Top soil replaced

Recontoured

Perennial forage re-established

Inspector Name: Welsh, Brian

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT