

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
02/25/2015

Document Number:
674300184

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>334777</u>	<u>334777</u>	<u>Spencer, Stan</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>96850</u>
Name of Operator:	<u>WPX ENERGY ROCKY MOUNTAIN LLC</u>
Address:	<u>1001 17TH STREET - SUITE #1200</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Lujan, Carlos		carlos.lujan@state.co.us	
, WPX		COGCCInspectionReports@wpxenergy.com	All inspections

Compliance Summary:

QtrQtr: NESW Sec: 4 Twp: 7S Range: 94W

Inspector Comment:

Inspection to assess future designation as Centralized E&P Facility. Base of steep cut slopes on south and west side of pit nearly abut edge of pit. This results in a potential concern regarding the Form 28 requirement for 10 ft fire lanes which must be addressed under the future permit application. See attached photos.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
263902	WELL	PR	10/21/2002	GW	045-08153	BERNKLAU RWF 24-4	PR	<input checked="" type="checkbox"/>
263904	WELL	PR	10/21/2002	GW	045-08155	BERNKLAU RWF 23-4	PR	<input checked="" type="checkbox"/>
263905	WELL	PR	10/21/2002	GW	045-08156	BERNKLAU RWF 323-4	PR	<input checked="" type="checkbox"/>
289191	WELL	PR	02/05/2007	GW	045-13685	WILLIAMS RWF 424-4	PR	<input checked="" type="checkbox"/>
289192	WELL	PR	02/05/2007	GW	045-13684	WILLIAMS RWF 524-4	PR	<input checked="" type="checkbox"/>
289193	WELL	PR	02/05/2007	GW	045-13683	WILLIAMS RWF 324-4	PR	<input checked="" type="checkbox"/>
289194	WELL	PR	02/05/2007	GW	045-13682	WILLIAMS RWF 612-4	PR	<input checked="" type="checkbox"/>
289195	WELL	PR	02/05/2007	GW	045-13681	WILLIAMS RWF 423-4	PR	<input checked="" type="checkbox"/>
414573	PIT	AC	03/22/2011		-	RWF 24-4	AC	<input type="checkbox"/>

Equipment:

Location Inventory

--

Inspector Name: Spencer, Stan

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 334777

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 263902 Type: WELL API Number: 045-08153 Status: PR Insp. Status: PR

Facility ID: 263904 Type: WELL API Number: 045-08155 Status: PR Insp. Status: PR

Facility ID: 263905 Type: WELL API Number: 045-08156 Status: PR Insp. Status: PR

Facility ID: 289191 Type: WELL API Number: 045-13685 Status: PR Insp. Status: PR

Facility ID: 289192 Type: WELL API Number: 045-13684 Status: PR Insp. Status: PR

Facility ID: 289193 Type: WELL API Number: 045-13683 Status: PR Insp. Status: PR

Facility ID: 289194	Type: WELL	API Number: 045-13682	Status: PR	Insp. Status: PR
Facility ID: 289195	Type: WELL	API Number: 045-13681	Status: PR	Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: Inspection to assess future designation as Centralized E&P Facility. Base of steep cut slopes on south and west side of pit nearly abut edge of pit. This results in a potential concern regarding the Form 28 requirement for 10 ft fire lanes which must be addressed under the future permit application. See attached photos.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use?

Production areas stabilized ?

1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____
 Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	414573	1631099	

414573

1631099

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674300185	West bank of pit looking south	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3560899
674300186	South bank looking east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3560900
674300187	Location from southwest looking northeast	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3560901