

Watson Ranch B Pad

Inspection# 675201278

Unmarked conductors.



Unmarked conductors.



Pipeline construction with
no construction BMPs along
south side of location.



Pipeline construction with
no construction BMPs along
south side of location.



Pipeline construction with
no construction BMPs along
south side of location.

