

Reference Area Photographs

Inspection Conducted on March 03, 2015

Encana

A28 595 Pad

Location ID #335804

Pit Facility ID #425547

Encana A28 595 pad




Sign at the entrance.



Lower right corner of photo: Location of pit #425547 (closed and backfilled).
Center of photo: stockpile of impacted material with in-situ remediation system (SVE).

Encana A28 595 pad



Active wells and in-situ remediation project.



View of the pad from top of stockpile with in-situ remediation. Stockpiled material has been contoured in preparation for future reclamation.