

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
03/10/2015

Document Number:
666800744

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>269871</u>	<u>324246</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10531</u>
Name of Operator:	<u>VANGUARD OPERATING LLC</u>
Address:	<u>5847 SAN FELIPE #3000</u>
City:	<u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Compliance Summary:

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/08/2013	670200939	PR	PR	SATISFACTORY	P		No
02/28/2012	663800180	PR	PR	SATISFACTORY			No
01/24/2012	659700056	PR	PR	SATISFACTORY	P		No
05/06/2010	200286521	PR	PR	SATISFACTORY			No
07/03/2008	200192035	PR	PR	SATISFACTORY			No
07/20/2007	200130531	CO	PR	ACTION REQUIRED			Yes
04/19/2007	200109949	PR	PR	SATISFACTORY	I	Pass	No
04/18/2007	200109861	PR	PR	SATISFACTORY	I	Pass	No
04/17/2007	200109253	PR	PR	SATISFACTORY	I	Pass	No
04/16/2007	200116846	PR	PR	SATISFACTORY			No
02/23/2007	200107886	CO	PR	SATISFACTORY	I	Pass	No
02/16/2007	200107882	CO	PR	SATISFACTORY	I	Pass	No
01/22/2007	200106955	PR	PR	SATISFACTORY	I	Pass	No
12/06/2006	200101392	CO	PR	SATISFACTORY	I	Pass	Yes
12/04/2006	200105596	CO	PR	SATISFACTORY		Pass	No
12/01/2006	200101325	PR	PR	SATISFACTORY	I	Pass	No
11/21/2006	200103617	CO	PR	SATISFACTORY	I	Pass	No
11/02/2006	200103680	CO	PR	SATISFACTORY		Pass	No
07/28/2006	200100321	PR	PR	SATISFACTORY	I	Pass	No
07/19/2006	200100012	CO	PR	SATISFACTORY	I	Pass	No

Inspector Name: Murray, Richard

07/13/2006	200100006	CO	PR	SATISFACTORY	I	Pass	No
06/12/2006	200097001	CO	PR	SATISFACTORY	I	Pass	No
04/22/2004	200053713	BH	PR	SATISFACTORY		Pass	No
02/19/2004	200052338	PR	WO	ACTION REQUIRED		Fail	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
269871	WELL	PR	03/19/2004	GW	045-09417	LAST DANCE 10-3	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Gas Meter Run	0				
Plunger Lift	1	SATISFACTORY			
Emission Control Device	1	SATISFACTORY			
Horizontal Heated Separator	1	SATISFACTORY			

Venting:

Yes/No	Comment
YES	Bradenhead valve open

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
------	------------------------------	---------	-------------------	---------

Predrill

Location ID: 269871

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 269871 Type: WELL API Number: 045-09417 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): Y _____

Comment: _____

Pilot: ON _____ Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

- 1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
- Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Culverts	Pass			
Seeding	Pass					
Compaction	Pass					

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT