

Vaneta 1-32D

Inspection# 673401898

Tanks and separator too close to wellhead.

3/10/2015

Inspection 673401898



Tanks and separator too close to wellhead.

12/3/2015

Inspection 673401503



Equipment stored on
location.

3/10/2015
Inspection 673401898



Equipment stored on
location.

12/3/2015
Inspection 673401503



Equipment stored on
location.

3/10/2015

Inspection 673401898



Equipment stored on
location.

12/3/2015

Inspection 673401503



Equipment stored on
location.

3/10/2015

Inspection 673401898



Equipment stored on
location.

12/3/2015

Inspection 673401503

