

A photograph showing a large, cylindrical, olive-green industrial tank on the left. A metal pipe runs horizontally across the gravel ground, connecting to the tank. The pipe has several valves and fittings. A dark, irregular oil spill is visible on the gravel ground near the pipe. In the background, there is a fence and a desert landscape.

oil spills on east side of tanks

03.12.2015 11:10