

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:  
03/11/2015

Document Number:  
668303356

Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

|                     |               |               |                    |                          |             |
|---------------------|---------------|---------------|--------------------|--------------------------|-------------|
| Location Identifier | Facility ID   | Loc ID        | Inspector Name:    | On-Site Inspection       | 2A Doc Num: |
|                     | <u>297142</u> | <u>310961</u> | <u>SCHURE, KYM</u> | <input type="checkbox"/> |             |

**Operator Information:**

|                       |  |
|-----------------------|--|
| OGCC Operator Number: | <u>60890</u>                                     |
| Name of Operator:     | <u>MOUNTAIN PETROLEUM CORP</u>                   |
| Address:              | <u>1801 BROADWAY STE 1250</u>                    |
| City:                 | <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name  | Phone              | Email               | Comment |
|---------------|--------------------|---------------------|---------|
| Probasco, Tim | 970-630-5095/96155 | tprob@plainstel.com |         |

**Compliance Summary:**

QtrQtr: NESW Sec: 10 Twp: 5N Range: 46W

**Inspector Comment:**

Site/Inventory Inspection

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status                            |
|-------------|------|--------|-------------|------------|-----------|---------------|--|
| 297142      | WELL | PR     | 02/01/2011  | GW         | 125-11354 | HARDING 23-10 | PR <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

**Lease Road:**

| Type   | Satisfactory/Action Required | comment                                   | Corrective Action | Date |
|--------|------------------------------|---|-------------------|------|
| Access | SATISFACTORY                 | No lease road, seasonal access, cropland. |                   |      |

| <b>Signs/Marker:</b> |                              |         |                   |         |
|----------------------|------------------------------|---------|-------------------|---------|
| Type                 | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD             | SATISFACTORY                 |         |                   |         |

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Good Housekeeping:</b> |                              |  |                   |         |
|---------------------------|------------------------------|--|-------------------|---------|
| Type                      | Satisfactory/Action Required | Comment                                    | Corrective Action | CA Date |
| DEBRIS                    | SATISFACTORY                 | Remove small pile of concrete at wellhead. |                   |         |

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Fencing/:</b> |                              |         |                   |         |
|------------------|------------------------------|---------|-------------------|---------|
| Type             | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                  | SATISFACTORY                 |         |                   |         |

| <b>Equipment:</b>  |   |                              |         |                   |         |
|--------------------|---|------------------------------|---------|-------------------|---------|
| Type               | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Gas Meter Run      | 1 | SATISFACTORY                 |         |                   |         |
| Vertical Separator | 1 | SATISFACTORY                 |         |                   |         |

| <b>Venting:</b> |         |
|-----------------|---------|
| Yes/No          | Comment |
|                 |         |

| <b>Flaring:</b> |                              |         |                   |         |
|-----------------|------------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                 |                              |         |                   |         |

**Predrill**

Location ID: 297142

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AV:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 297142 Type: WELL API Number: 125-11354 Status: PR Insp. Status: PR

**Producing Well**

Comment: Flowing gas well

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**  
DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:** \_\_\_\_\_

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_  
Comment: \_\_\_\_\_  
Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment:

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment:

Corrective Action:  Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other            | Pass            |                         |                       |               |                          |         |

S/A/V: SATISFACTOR \_\_\_\_\_ Corrective Date: \_\_\_\_\_  
Y \_\_\_\_\_

Comment: Utilize BMP's for control and maintenance of stormwater surface erosion.

CA:

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 668303357    | Harding 23-10 Wellhead/Sign | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3569142">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3569142</a> |
| 668303358    | Harding 23-10 Wellhead area | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3569143">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3569143</a> |