

Voloshin 3-25

Inspection# 673401910

Stored equipment. Soil sloughing onto location, no visible BMPs.



Tubing stored on location.



Equipment stored on location.



Fluid at wellhead. No chemical containment.



No chemical containment.



Berm not compacted.



Rill leaving location.



What is in this “soil” pile? It appears similar to cuttings materials, fluid in pile has sheen and some visible hydrocarbon.

