

Diamond Elk ID#334705

Inspection# 675201299

Dirt pile on location.



Dirt pile on location with no
stormwater BMPs.



Sediment migration from
pile towards vegetation.

