



Photo 1. View of kochia debris along southern fenceline facing eastward.





Photo 2. View of boundary between vegetated (on left) and unvegetated (on right) areas within the western portion of the interim reclamation area. Grey vegetation on right is a dense population of kochia.



Photo 3. View of two patches of killed vegetation (in mid ground and back ground) adjacent to the western edge of the working area of the well pad.





Photo 4. View of stormwater erosion on southwestern corner of working area of well pad.