

**FORM
INSP**
Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
03/17/2015

Document Number:
670900379

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>432992</u>	<u>432988</u>	<u>Peterson, Tom</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10311</u>
Name of Operator:	<u>SYNERGY RESOURCES CORPORATION</u>
Address:	<u>20203 HIGHWAY 60</u>
City:	<u>PLATTEVILLE</u> State: <u>CO</u> Zip: <u>80651</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Pennington, Dave		dpennington@syrginfo.com	All inspections

Compliance Summary:

QtrQtr:	<u>SWNW</u>	Sec:	<u>5</u>	Twp:	<u>2N</u>	Range:	<u>68W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/24/2015	670900209	PR	PR	ACTION REQUIRED			No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
432982	WELL	XX	05/19/2013	LO	123-37389	SRC Union 11-5D	XX	<input type="checkbox"/>
432984	WELL	AL	01/17/2014	LO	123-37391	SRC Union 5FD	AL	<input type="checkbox"/>
432986	WELL	XX	05/19/2013	LO	123-37393	SRC Union 5JD	XX	<input type="checkbox"/>
432989	WELL	AL	01/17/2014	LO	123-37395	SRC Union 12-5D	AL	<input type="checkbox"/>
432990	WELL	PR	09/05/2014	LO	123-37396	SRC Union 12-5CHZ	PR	<input checked="" type="checkbox"/>
432991	WELL	PR	09/05/2014	LO	123-37397	SRC Union A-5NHZ	PR	<input checked="" type="checkbox"/>
432992	WELL	PR	09/05/2014	LO	123-37398	SRC Union A-5CHZ	PR	<input checked="" type="checkbox"/>
432993	WELL	PR	11/10/2014	LO	123-37399	SRC Union C-5NHZ	PR	<input checked="" type="checkbox"/>
432994	WELL	PR	09/05/2014	LO	123-37400	SRC Union 12-5NHZ	PR	<input checked="" type="checkbox"/>
435075	WELL	PR	09/05/2014	LO	123-38451	SRC Union C-5CHZ	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Inspector Name: Peterson, Tom

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>10</u>	Production Pits: _____
Condensate Tanks: <u>22</u>	Water Tanks: <u>11</u>	Separators: <u>10</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: <u>2</u>	VOC Combustor: <u>12</u>	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
STORAGE OF SUPL	SATISFACTORY	Items noted on prior inspection document #670900209 have been corrected		
UNUSED EQUIPMENT	SATISFACTORY	Items noted on prior inspection document #670900209 have been corrected		

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 432992

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 432990 Type: WELL API Number: 123-37396 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

BradenHead

Comment: **Bradenhead is exposed at surface**

CA: _____

CA Date: _____

Facility ID: 432991 Type: WELL API Number: 123-37397 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is exposed at surface

CA:

CA Date:

Facility ID: 432992 Type: WELL API Number: 123-37398 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is exposed at surface

CA:

CA Date:

Facility ID: 432993 Type: WELL API Number: 123-37399 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is exposed at surface

CA:

CA Date:

Facility ID: 432994 Type: WELL API Number: 123-37400 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is exposed at surface

CA:

CA Date:

Facility ID: 435075 Type: WELL API Number: 123-38451 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is exposed at surface

CA:

CA Date:

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Complaint:

Tracking Num	Category	Assigned To	Description	Incident Date
200407635	NOISE	Gomez, Jason	On 6-13-2014, the COGCC office received a noise complaint from Jenn Medoff at 11690 Montgomery Circle Longmont CO. The complainant indicated she could here noise coming from a well location with a flare which is located to the west of her home. The complainant was also worried about the flame burning on location which she believed to be causing the noise.	06/13/2014

Emission Control Burner (ECB): Y
 Comment: _____
 Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: IRRIGATED
 Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____

Inspector Name: Peterson, Tom

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
670900379	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3571270