

N. Vega Pad 5A

Inspection# 675201312

Tanks pictured on original inspection.



Tanks still on location at time of follow up inspection



Unused equipment pictured
on original inspection.



Unused equipment pictured
on follow up inspection.



Trash in tank containment
pictured on original
inspection.



Trash at time of follow up
inspection.

