

FORM  
5Rev  
09/14

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400581095

Date Received:

03/31/2014

## DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type ☒ Final completion ☐ Preliminary completion

OGCC Operator Number: 100322

Contact Name: Kathleen Mills

Name of Operator: NOBLE ENERGY INC

Phone: (720) 587-2226

Address: 1625 BROADWAY STE 2200

Fax: (303) 228-4286

City: DENVER State: CO Zip: 80202

API Number 05-123-37980-00

County: WELD

Well Name: SCOOTER D

Well Number: 18-79HN

Location: QtrQtr: NWNW Section: 18 Township: 3N Range: 64W Meridian: 6

Footage at surface: Distance: 305 feet Direction: FNL Distance: 657 feet Direction: FWL

As Drilled Latitude: 40.231669 As Drilled Longitude: -104.600253

## GPS Data:

Date of Measurement: 11/04/2013 PDOP Reading: 2.8 GPS Instrument Operator's Name: LYNAE HAMMER

\*\* If directional footage at Top of Prod. Zone Dist.: 879 feet. Direction: FNL Dist.: 77 feet. Direction: FEL

Sec: 13 Twp: 3N Rng: 65W

\*\* If directional footage at Bottom Hole Dist.: 537 feet. Direction: FSL Dist.: 84 feet. Direction: FEL

Sec: 13 Twp: 3N Rng: 65W

Field Name: WATTENBERG

Field Number: 90750

Federal, Indian or State Lease Number:

Spud Date: (when the 1st bit hit the dirt) 12/13/2013 Date TD: 12/21/2013 Date Casing Set or D&amp;A: 12/23/2013

Rig Release Date: Per Rule 308A.b.

## Well Classification:

☐ Dry ☒ Oil ☐ Gas/Coalbed ☐ Disposal ☐ Stratigraphic ☐ Enhanced Recovery ☐ Storage ☐ Observation

Total Depth MD 11410 TVD\*\* 6974 Plug Back Total Depth MD 11376 TVD\*\* 6974

Elevations GR 4811 KB 4827 Digital Copies of ALL Logs must be Attached per Rule 308A ☒

## List Electric Logs Run:

CBL, MUD. GR

## CASING, LINER AND CEMENT

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	26	16	42	0	96	80	0	96	VISU
SURF	13+3/4	9+5/8	36	0	828	418	0	828	VISU
1ST	8+3/4	7	26	0	7,423	680	1,300	7,423	CALC
1ST LINER	6+1/8	4+1/2	11.6	7293	11,377	0			

## STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: \_\_\_\_\_

Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom

Details of work:

## FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analysis must be submitted to COGCC)
	Top	Bottom	DST	Cored	
PIERRE	2,764				
PARKMAN	3,765				
SUSSEX	4,443				
SHANNON	4,984				
TEEPEE BUTTES	6,159				
NIOBRARA	6,959				

Comment:

GPS TAKEN ON CONDUCTOR

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Kathleen Mills

Title: Regulatory Analyst Date: 3/31/2014 Email: kmills@nobleenergyinc.com

### Attachment Check List

Att Doc Num	Document Name	attached ?	
<u>Attachment Checklist</u>			
400581109	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
400581108	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<u>Other Attachments</u>			
400581095	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400581110	DIRECTIONAL DATA	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400581134	PDF-CEMENT BOND	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400581136	PDF-MUD	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400581152	LAS-MUD	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400581153	PDF-MUD	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400581155	LAS-MUD	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400581157	LAS-GAMMA RAY	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400581160	PDF-GAMMA RAY	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400581161	PDF-GAMMA RAY	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Directional survey .pdf corrupted. Contacted operator. Returned to draft.	3/19/2015 9:34:38 AM

Total: 1 comment(s)