



Photo 1. View of western portion of interim reclamation area from southwestern corner facing northward. Grasses appear to be grazed.



Photo 2. View of northern portion of interim reclamation area from northwestern corner facing eastward. Revegetation grasses appear to be grazed.





Photo 3. View of working area of well pad from northwestern corner facing center. Cattle feed barrels can be seen on right and upper-center of photo. Deep cow punch and large quantity of manure can also be seen.