

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
03/19/2015

Document Number:
668603443

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>204349</u>	<u>320664</u>	<u>QUINT, CRAIG</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10194</u>
Name of Operator:	<u>JFH DISPOSAL LLC</u>
Address:	<u>P O BOX 967</u>
City:	<u>STRASBURG</u> State: <u>CO</u> Zip: <u>80136</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Hickey, John	(970) 390-8562	ddwater@tds.net	

Compliance Summary:

QtrQtr: NESE Sec: 8 Twp: 4S Range: 62W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/09/2014	673706790	IJ	IJ	ACTION REQUIRED			No
06/04/2014	673703783	IJ	SI	ACTION REQUIRED			No
06/19/2013	668300384	IJ	UN	SATISFACTORY	P		No
07/23/2012	667600593	IJ	SI	SATISFACTORY	P		No
08/19/2011	200318956	RT	AO	SATISFACTORY			No
08/20/2010	200267451	MI	SI	SATISFACTORY			No
08/19/2010	200267445	MI	SI	SATISFACTORY			No
08/12/2009	200217005	RT	AC	SATISFACTORY			No
08/11/2008	200194037	RT	AC	SATISFACTORY			No
07/24/2007	200116042	RT	AC	SATISFACTORY		Pass	No
06/20/2006	200093852	RT	AC	SATISFACTORY		Pass	No
07/26/2005	200074231	MI	AC	SATISFACTORY		Pass	No
08/03/2004	200057583	RT	AC	SATISFACTORY		Pass	No
08/19/2003	200042994	RT	AC	SATISFACTORY		Pass	No
07/10/2002	200028694	RT	AC	ACTION REQUIRED		Fail	Yes
07/24/2001	1084296	MI	AC	ACTION REQUIRED		Fail	Yes
08/29/2000	896184	MI	AC	SATISFACTORY		Pass	No
08/02/2000	896181	MI	AC	ACTION REQUIRED		Fail	Yes
03/22/1996	500134390	ES	AC			Fail	Yes

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
150319	UIC DISPOSAL	AC	05/07/1991		-	PRITCHETTE-GREEN C-1	PA	<input checked="" type="checkbox"/>
204349	WELL	SI	11/25/2014	OW	005-06434	PRITCHETTE-GREEN C-1	PA	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 204349

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:**

CA: **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 150319 Type: UIC API Number: - Status: AC Insp. Status: PA

Facility ID: 204349 Type: WELL API Number: 005-06434 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: BASIC

Contractor Phone: 970-867-2766

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 850/260

Cement Volume (sx): _____

Good Return During Job: YES

Cement Type: CLASS G COM

Comment: ARRIVE 7:15 AM, RIH W/TBG, TAG CEMENT @ 1170', POOH W/TBG TO 865', RU BASIC, UNABLE TO START BULK TRUCK COMPRESSOR ENGINE, RIG UP WATER TRUCK AIR TO BULK TRUCK, (10:30) PUMP 25 SX CMT (CLASS G COM W/2% CAL), DIS W/2.5 BBL WATER, POOH W/TBG, RU BASIC, BULL HEAD 125 SX CMT DOWN 5 1/2 WITH CMT RETURNS TO SURFACE.

Workover

Comment: **MATCO RIG 102 TRIPPING TUBING FOR PLUGGING OPERATION.**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____
 Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Inspector Name: QUINT, CRAIG

Corrective Action: _____ Date _____
Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT