



photo 1: Well sign, New Elk 26-12



photo 2: North side of the location facing southwest.



photo 3: West side of the location facing south..



photo 4: West side of the location facing east.



photo 5: Facing east towards the access road.



photo 6: The northeast corner of the location shows signs of erosion.



photo 7: Material sloughing off the northeast corner of the location.



photo 8: Erosion channel along the access road.