



Bison Oil Well Cementing, Inc
1738 Wynkoop St., Ste. 102
Denver, CO 80202
303-296-3010
www.Bisonoilwell.com

Cementing Customer Satisfaction Survey

Service Date 10-2-13
Invoice Amount _____
Well Name CBS 34-16
Well Location _____
County Weld
SEC/TWP/RNG 34 9N 59W
State CO
Supervisor Name Monte

Invoice Number 12712
Well Permit Number _____
Well Type Cas
Well Number 34-16
Lease _____
Job Type P&A
Company Name Noble
Customer Representative Chuck
Customer Phone Number _____

Employee Name

Exposure Hours (Per Employee)

Total Exposure Hours

Did we encounter any problems on this job? Yes / No

To Be Completed By Customer

Rating/Description

- 5 - Superior Performance (Established new quality / performance standards)
- 4 - Exceeded Expectations (Provided more than what was required / expected)
- 3 - Met Expectations (Did what was expected)
- 2 - Below Expectations (Job problems / failures occurred [* Recovery made])
- 1 - Poor Performance (Job problems / failures occurred [* Some recovery made])

* Recovery: resolved issue(s) on jobsite in a timely and professional manner

Opportunity

- Best Practices
- Potential Best Practice
- Prevention/Improvement

RATING / CATEGORY

- _____ Personnel -
- _____ Equipment -
- _____ Job Design -
- _____ Product / Material -
- _____ Health & Safety -
- _____ Environmental -
- _____ Timeliness -
- _____ Condition / Appearance -
- _____ Communication -
- _____ Improvement -

CUSTOMER SATISFACTION RATING

- Did our personnel perform to your satisfaction ?
- Did our equipment perform to your satisfaction ?
- Did we perform the job to the agreed upon design ?
- Did our products and materials perform as you expected ?
- Did we perform in a safe and careful manner (Pre / post mtgs, PPE, TSMR, etc..) ?
- Did we perform in an environmentally sound manner (Spills, leaks, cleanup, etc..) ?
- Was job performed as scheduled (On time to site, accessible to customer, completed when expected)?
- Did the equipment condition and appearance meet your expectation?
- How well did our personnel communicate during mobilization, rig up, and job execution?
- What can we do to improve our service?

Please Circle:

- Yes / No - Did an accident or injury occur?
- Yes / No - Did an injury requiring medical treatment occur?
- Yes / No - Did a first-aid injury occur?
- Yes / No - Did a vehicle accident occur?
- Yes / No - Was a post-job safety meeting held?

Additional Comments:

Please Circle:

- Yes / No - Was a pre-job safety meeting held?
- Yes / No - Was a job safety analysis completed?
- Yes / No - Were emergency services discussed?
- Yes / No - Did environmental incident occur?
- Yes / No - Did any near misses occur?

THE INFORMATION HEREIN IS CORRECT -

Customer Representative's Signature

Date

Any additional Customer Comments or HSE concerns should be described on the back of this form

BISON OIL WELL CEMENTING, INC.

1547 Gaylord Street
Denver, Colorado 80206
Phone: 303-296-3010
Fax: 303-298-8143
E-mail: bisonoil1@qwestoffice.net



INVOICE #
LOCATION
FOREMAN

12712
115414
monte

Treatment Report Page 2

DESCRIPTION OF JOB EVENTS

Safety Meeting	9/5	Displace 1			Displace 2			Displace 3			Displace 4			Displace 5			Displace 5		
MIRU	800	BBLs	Time	PSI	BBLs	Time	PSI	BBLs	Time	PSI	BBLs	Time	PSI	BBLs	Time	PSI	BBLs	Time	PSI
CIRCULATE	934	0	1008	0	0	1202	100	0	10	0	0	10	0	0	10	0	0	10	0
Drop Plug		10	1012	0	10	1203	100	20	20	20	20	20	20	20	20	20	20	20	20
		120	1016	130	30			30	30	30	30	30	30	30	30	30	30	30	30
		30			40			40	40	40	40	40	40	40	40	40	40	40	40
		40			50			50	50	50	50	50	50	50	50	50	50	50	50
M & P		50			60			60	60	60	60	60	60	60	60	60	60	60	60
		60			70			70	70	70	70	70	70	70	70	70	70	70	70
Time	957	70			80			80	80	80	80	80	80	80	80	80	80	80	80
Sacks	100	80			90			90	90	90	90	90	90	90	90	90	90	90	90
		90			100			100	100	100	100	100	100	100	100	100	100	100	100
		100			110			110	110	110	110	110	110	110	110	110	110	110	110
		110			120			120	120	120	120	120	120	120	120	120	120	120	120
		120			130			130	130	130	130	130	130	130	130	130	130	130	130
		130			140			140	140	140	140	140	140	140	140	140	140	140	140
		140			150			150	150	150	150	150	150	150	150	150	150	150	150
		150																	

Notes:

1st Plug
circulate 8 bbls Ahead mix + Pump 100 SKS G West 15.8 1.17 yield 5 gal pack H70
displace 14.7 bbls H70 3007 ft deep
2nd Plug
circulate 8 bbls ahead mix + Pump 340 SKS BFLTH 3970 BFLTH 15.2 1.27 yield 5.89 H70
displace 2.7

X Work Performed
X Consultant
Title
Date 10-2-13