FORM INSP Rev 05/11

# State of Colorado
# Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|---|---|---|---|
| | | | |

Inspection Date: 03/27/2015

Document Number: 673401972

Overall Inspection: SATISFACTORY

## FIELD INSPECTION FORM

| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection ☐ |
|---|---|---|---|---|
| | 212432 | 324686 | Waldron, Emily | 2A Doc Num: |

**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---|---|---|---|
| Jones, Alan | 661-444-0999 | jaj@bonanzacrk.com | All Inspections |

**Compliance Summary:**

QtrQtr: NWSE Sec: 27 Twp: 9N Range: 78W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|---|---|---|---|---|---|---|---|
| 05/05/2014 | 673400527 | SI | TA | SATISFACTORY | | | No |
| 09/20/2010 | 200276874 | PR | SI | SATISFACTORY | | | No |
| 08/13/2002 | 200030552 | ID | TA | SATISFACTORY | | Pass | No |
| 07/12/2000 | 200007910 | PR | PR | | | Pass | No |
| 08/05/1999 | 500144217 | PR | SI | | | Pass | No |
| 08/13/1996 | 500144216 | PR | PR | | | Pass | No |
| 09/09/1994 | 500144215 | | PR | | | Pass | No |

**Inspector Comment:**

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|---|---|---|---|---|---|---|---|---|
| 212432 | WELL | SI | 08/08/2014 | OW | 057-06325 | FEDERAL 10-27 | PA | ☒ |

**Equipment:**

Location Inventory

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Special Purpose Pits: | | Drilling Pits: | | Wells: | | Production Pits: | |
| Condensate Tanks: | | Water Tanks: | | Separators: | | Electric Motors: | |
| Gas or Diesel Mortors: | | Cavity Pumps: | | LACT Unit: | | Pump Jacks: | |
| Electric Generators: | | Gas Pipeline: | | Oil Pipeline: | | Water Pipeline: | |
| Gas Compressors: | | VOC Combustor: | | Oil Tanks: | | Dehydrator Units: | |
| Multi-Well Pits: | | Pigging Station: | | Flare: | | Fuel Tanks: | |

Inspector Name: Waldron, Emily

## Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment:

Corrective Action:

| **Spills:** | | | | |
|---|---|---|---|---|
| Type | Area | Volume | Corrective action | CA Date |

☐ Multilple Spills and Releases?

| **Venting:** | |
|---|---|
| Yes/No | Comment |
| | |

| **Flaring:** | | | | |
|---|---|---|---|---|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

## Predrill

Location ID: 212432

**Site Preparation:**

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

**S/A/V:** _____

Corrective Action: _____ Date: _____ CDP Num.: _____

**Form 2A COAs:**

**S/A/V:** _____ **Comment:** _____

**CA:** _____ **Date:** _____

**Wildlife BMPs:**

**S/A/V:** _____ **Comment:** _____

**CA:** _____ **Date:** _____

**Stormwater:**

**Comment:** _____

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

## Facility

Facility ID: 212432 Type: WELL API Number: 057-06325 Status: SI Insp. Status: PA

## Environmental

**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

**Water Well:**

Inspector Name: Waldron, Emily

DWR Receipt Num: Owner Name: GPS : Lat Long

**Field Parameters:**

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Inspector Name: Waldron, Emily

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built Fail

Access Roads Regraded Fail Contoured Fail Culverts removed Fail

Gravel removed Fail

Location and associated production facilities reclaimed In Locations, facilities, roads, recontoured In

Compaction alleviation Fail Dust and erosion control _____

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present Pass Subsidence Pass

Comment: No reclamation apparent. Deadmen still on location.

Corrective Action: Date _____

Overall Final Reclamation Fail Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|---|---|---|---|---|---|---|
| | | | | | | |

S/A/V: _____ Corrective Date: _____

Comment:

CA:

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment | User | Date |
|---|---|---|
| Well plugged 11/19/2014 (Form 6 document number 400752566) no final reclamation observed. | waldrone | 03/27/2015 |