

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/01/2015

Document Number:

674102174

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	418627	319437	Rickard, Jeff	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	All PDC inspection

Compliance Summary:QtrQtr: NESW Sec: 21 Twp: 4N Range: 67W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
243482	WELL	PR	04/23/2007	OW	123-11273	BUNYAN 1	PR	<input checked="" type="checkbox"/>
418627	WELL	PR	07/31/2011	OW	123-31963	Walters 21ODU	PR	<input checked="" type="checkbox"/>
418641	WELL	PR	07/31/2011	OW	123-31966	Walters 23-21DU	PR	<input checked="" type="checkbox"/>
418642	WELL	PR	08/31/2011	OW	123-31967	Ryland 20XD	PR	<input checked="" type="checkbox"/>
418643	WELL	PR	08/31/2011	OW	123-31968	Wedco 13-21DU	PR	<input checked="" type="checkbox"/>
418754	WELL	PR	08/31/2011	OW	123-31996	Wedco 14-21DU	PR	<input checked="" type="checkbox"/>
418759	WELL	PR	07/31/2011	OW	123-31998	Walters 21LDU	PR	<input checked="" type="checkbox"/>
418760	WELL	PR	10/01/2011	OW	123-31999	Ryland 20YD	PR	<input checked="" type="checkbox"/>
418762	WELL	PR	07/31/2011	OW	123-32000	Walters 21QDU	PR	<input checked="" type="checkbox"/>
418767	WELL	PR	08/30/2011	OW	123-32001	Walters 24-21DU	PR	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: Rickard, Jeff

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>10</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>2</u>	Separators: <u>4</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>3</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
--------	---------

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
------	------------------------------	---------	-------------------	---------

Predrill

Location ID: 418627

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 243482 Type: WELL API Number: 123-11273 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA: _____

CA Date: _____

Facility ID: 418627 Type: WELL API Number: 123-31963 Status: PR Insp. Status: PR

Producing WellComment: **PR****BradenHead**Comment: **Braden head is exposed at surface.**

CA:

CA Date:

Facility ID: 418641 Type: WELL API Number: 123-31966 Status: PR Insp. Status: PR**Producing Well**Comment: **PR****BradenHead**Comment: **Braden head is exposed at surface.**

CA:

CA Date:

Facility ID: 418642 Type: WELL API Number: 123-31967 Status: PR Insp. Status: PR**Producing Well**Comment: **PR****BradenHead**Comment: **Braden head is exposed at surface.**

CA:

CA Date:

Facility ID: 418643 Type: WELL API Number: 123-31968 Status: PR Insp. Status: PR**Producing Well**Comment: **PR****BradenHead**Comment: **Braden head is exposed at surface.**

CA:

CA Date:

Facility ID: 418754 Type: WELL API Number: 123-31996 Status: PR Insp. Status: PR**Producing Well**Comment: **PR****BradenHead**Comment: **Braden head is exposed at surface.**

CA:

CA Date:

Facility ID: 418759 Type: WELL API Number: 123-31998 Status: PR Insp. Status: PR**Producing Well**Comment: **PR**

Inspector Name: Rickard, Jeff

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418760 Type: WELL API Number: 123-31999 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418762 Type: WELL API Number: 123-32000 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418767 Type: WELL API Number: 123-32001 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB): Y

Comment:

Inspector Name: Rickard, Jeff

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Inspector Name: Rickard, Jeff

Access Roads Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____
Comment: _____
Corrective Action: _____ Date _____
Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____
CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT