

Inspector Name: Rains, Bill

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:
03/31/2015Document Number:
673900904Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	298382	302386	Rains, Bill	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 10261

Name of Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC

Address: 730 17TH ST STE 610

City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Blyth, Tom	(303) 893-2503	tblyth@bayswater.us	All inspections

Compliance Summary:QtrQtr: NWSE Sec: 30 Twp: 6N Range: 63W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
298382	WELL	PR	02/10/2014	OW	123-29045	FAIRMEADOWS 4-30	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>1</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>1</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	PIPE		
Equipment:				
Type	#	Satisfactory/Action Required	Comment	CA Date
Ancillary equipment	1	SATISFACTORY	METH PUMP AND DRUM	
Plunger Lift	1	SATISFACTORY		
Venting:				
Yes/No	Comment			
NO				
Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Predrill				
Location ID: 298382				
Site Preparation:				
Lease Road Adeq.:		Pads:	Soil Stockpile:	
S/AV:				
Corrective Action:		Date:	CDP Num.:	
Form 2A COAs:				
Group	User	Comment	Date	
OGLA	koepsear	Location is in a sensitive area because of shallow groundwater; therefore, either a lined drilling pit or closed loop system is required.	06/02/2011	
S/AV:		Comment:		
CA:		Date:		
Wildlife BMPs:				
BMP Type	Comment			
Storm Water/Erosion Control	Stormwater ? When site disturbance is greater than one acre, a stormwater discharge permit will be completed per state regulations ? Stormwater best management practices will be installed ? All stormwater best management practices will remain in place until final stabilization is achieved.			

Inspector Name: Rains, Bill

Construction	Noxious Weeds ? Site will be inspected to document weed infested areas ? Prompt action will be taken to mitigate infested areas. ? All noxious weeds identified will not be allowed to reach the flowering or seed dispersal stage. ? Vehicles will not be allowed to drive through weed infested areas. ? Machinery will not be parked in weed infested areas. ? Vehicles sent off site regularly will be inspected to assure that undercarriages and grill works are kept free of weed seed. ? Undercarriages of vehicles or machinery potentially contaminated with noxious weed seeds will be washed before entry is made into non infested areas.
Storm Water/Erosion Control	Fugitive Dust and Vehicle Tracking ? Traffic speeds will be limited to control fugitive dust ? Watering will be completed to control fugitive dust as needed ? Graveled entries will be provided for vehicle tracking control ? Furrowing of disturbed soil will be provided at right angles to prevailing winds as needed ? Silt fences will be installed for wind breaks as need
General Housekeeping	Solid Waste ? The site will be cleaned of all trash and waste as soon as practical ? All waste will be stored in sealed containers until it can be disposed of appropriately ? Solid waste will be removed from the site and disposed of per state regulations for solid waste
Drilling/Completion Operations	Spill Prevention ? All materials, waste, and fluids kept on site will be stored in an appropriate manner to prevent contamination with the environment ? If a spill occurs, it will be cleaned up using absorbent material and by removing the contaminated soil ? Any contaminated soil will be placed in a sealed container that can be disposed of appropriately ? All efforts will be made to prevent the spill from migrating off-site or coming into contact with stormwater runoff ? The Spill Control and Countermeasures plan, if applicable, will address and control all spill procedures
Final Reclamation	Reclamation ? Interim and or final reclamation of the site will be completed per the Colorado Oil and Gas Conservation Commission (COGCC) rules and regulations.

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 298382 Type: WELL API Number: 123-29045 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD EXPOSED TO SURFACE

CA:

CA Date:

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: IRRIGATED

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? Pass CM

CA CA Date

Guy line anchors removed? Pass CM

Inspector Name: Rains, Bill

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Inspector Name: Rains, Bill

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT