

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

03/26/2015

Document Number:

668402835

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 229318      | 314696 | BROWNING, CHUCK | <input type="checkbox"/> |             |

**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON PRODUCTION COMPANYAddress: 100 CHEVRON RDCity: RANGELY State: CO Zip: 81648

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment               |
|-----------------|--------------|----------------------------|-----------------------|
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector       |
| Peterson, Diane | 970-675-3842 | dlpe@chevron.com           | Regulatory Specialist |

**Compliance Summary:**QtrQtr: SWSW Sec: 14 Twp: 2N Range: 103W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 05/20/2014 | 668402128 | IJ         | AC          | SATISFACTORY                  | P        |                | No              |
| 04/12/2013 | 668401103 | IJ         | AC          | SATISFACTORY                  | P        |                | No              |
| 05/23/2012 | 668400519 | IJ         | SI          | SATISFACTORY                  |          |                | No              |
| 05/18/2011 | 200310997 | RT         | AC          | SATISFACTORY                  |          |                | No              |
| 06/09/2009 | 200213872 | RT         | AC          | SATISFACTORY                  |          |                | No              |
| 05/15/2008 | 200192275 | MI         | AC          | SATISFACTORY                  |          |                | No              |
| 05/10/2007 | 200112789 | RT         | AC          | SATISFACTORY                  |          | Pass           | No              |
| 05/16/2006 | 200092800 | RT         | AC          | SATISFACTORY                  |          | Pass           | No              |
| 05/12/2005 | 200073188 | RT         | AC          | SATISFACTORY                  |          | Pass           | No              |
| 05/10/2004 | 200057680 | RT         | AC          | SATISFACTORY                  |          | Pass           | No              |
| 05/13/2003 | 200041640 | MI         | AC          | SATISFACTORY                  |          | Pass           | No              |
| 05/15/2002 | 200026581 | RT         | AC          | SATISFACTORY                  |          | Pass           | No              |
| 05/23/2001 | 200019037 | RT         | AC          | SATISFACTORY                  |          | Pass           | No              |
| 05/30/2000 | 200009082 | RT         | AC          | SATISFACTORY                  |          | Pass           | No              |

**Inspector Comment:**UIC Routine inspection.**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|-------------------------------------|
| 229318      | WELL | IJ     | 08/01/1993  | DSPW       | 103-06419 | MCLAUGHLIN, A C 55X | AC          | <input checked="" type="checkbox"/> |

**Equipment:**Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location****Lease Road:**

| Type   | Satisfactory/Action Required | comment | Corrective Action | Date |
|--------|------------------------------|---------|-------------------|------|
| Main   | SATISFACTORY                 |         |                   |      |
| Access | SATISFACTORY                 |         |                   |      |

**Signs/Marker:**

| Type     | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY                 |         |                   |         |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?**Venting:**

| Yes/No | Comment |
|--------|---------|
| NO     |         |

**Flaring:**

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
|      |                              |         |                   |         |

**Predrill**

Location ID: 229318

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 229318 Type: WELL API Number: 103-06419 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_

Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**Inj./Tube: Pressure or inches of Hg 1481  
(e.g. 30 psig or -30" Hg)Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
Inj Zone: WEBR

TC: Pressure or inches of Hg 0

Previous Test Pressure \_\_\_\_\_ Last MIT: 04/12/2013

Brhd: Pressure or inches of Hg 0

Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: UIC Routine inspection. Casing blowdown 0 sec.

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_

Tbg psi: \_\_\_\_\_

Csg psi: \_\_\_\_\_

BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

- 1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_ Pass \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            | Gravel                  | Pass                  | SI            | Pass                     |         |

Inspector Name: BROWNING, CHUCK

S/A/V: SATISFACTOR  
Y

Corrective Date: \_\_\_\_\_

Comment:

CA:

**Pits:** ☐ NO SURFACE INDICATION OF PIT