

Elk Springs Unit 23B-8

Inspection# 673401986

No wellhead sign. Stained soil.



Stained soil, path of stained soil leading away from wellhead.

