



**photo 1:** Well sign, Lorencito 15-6-34-66



**photo 2:** Unused pipe remains on the location.





**photo 3:** Pit at the northeast side of location.



**photo 4:** East side of the location facing east. Disturbed area has recently been seeded and mulched.





**photo 5:** The pit to the southwest of the location has recently been closed and reclaimed.



**photo 6:** Weeds (mullein) was found growing along the southwest side of the pad.