

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax:(303)894-2109



FOR OGCC USE ONLY
Received 7/14/2013
Document 2142813

Spill report taken by:

FACILITY ID:

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: _____ OGCC Operator No: _____	Phone Numbers
Address: _____	No: _____
City: _____ State: _____ Zip: _____	Fax: _____
Contact Person: _____	E-Mail: _____

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: _____ Facility Name & No.: _____	County: _____
Type of Facility (well, tank battery, flow line, pit): _____	QtrQtr: _____ Section: _____
Well Name and Number: _____	Township: _____ Range: _____
API Number: _____	Meridian: _____
Specify volume spilled and recovered (in bbls) for the following materials:	
Oil spilled: _____ Oil recov'd: _____ Water spilled: _____ Water recov'd: _____ Other spilled: _____ Other recov'd: _____	
Ground Water impacted? Yes No	Surface Water impacted? Yes No
Contained within berm? Yes No	Area and vertical extent of spill: _____ x _____
Current land use: _____	Weather conditions: _____
Soil/geology description: _____	
IF LESS THAN A MILE , report distance IN FEET to nearest.... Surface water: _____ wetlands: _____ buildings: _____	
Livestock: _____ water wells: _____ Depth to shallowest ground water: _____	
Cause of spill (e.g., equipment failure, human error, etc.): _____ Detailed description of the spill/release incident: _____	

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):

Describe any emergency pits constructed:

How was the extent of contamination determined:

Further remediation activities proposed (attach separate sheet if needed):

Describe measures taken to prevent problem from reoccurring:

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response

Spill/Release Tracking No: 2142813

**IONE 62N66W / NUNE /SEC 2 HZ PAD (Facility ID # 430283) – FORM 19 –
NARRATIVE DOCUMENT**

Date of Incident – 07/14/2013

Detailed description of the spill/release incident:

In the early hours of Sunday July 14th, 2013 the tanks holding oil at the Ione 62N66W / NUNE /SEC 2 HZ pad overfilled resulting in a release of approximately 37 BBLs of condensate within the secondary containment and on the surface immediately adjacent to the containment. An internal investigation determined that an automation valve was not turned on before the end of a shift on Saturday July 13th.

Describe immediate response (how stopped, contained and recovered):

The wells were shut in, a vacuum truck was dispatched to the site, and the standing condensate was removed from the surface.

Describe any emergency pits constructed:

NA

How was the extent of contamination determined?:

The extent will be determined when remediation activities begin this week. Soils will be screened with a PID meter, excavated, and disposed of at Buffalo Ridge landfill in Weld County. Confirmation soil samples will be collected to demonstrate COGCC Table 910-1 compliance.


Further remediation activities proposed (attach separate sheet if needed):

NA

Describe measures taken to prevent problem from reoccurring:

Additional training will be conducted for pumpers that operate high capacity facilities.






Copyright © 2011 National Geographic Society, i-cubed

Legend

- IONE 62N66W / NWNE / SEC 2 HZ PAD



IONE 62N66W / NWNE / SEC 2 HZ PAD
Weld County, Colorado