



Soil, Water & Forage Analytical Laboratory

Oklahoma State University Division of Agricultural Sciences and Natural Resources
045 Agricultural Hall
Stillwater, OK 74078
E-mail: soiltesting@okstate.edu
Website: www.soiltesting.okstate.edu

SOIL TEXTURE REPORT

TEXAS CO EXT OFC
PO BOX 320
301 N MAIN
GUYMON, OK 73942
(580) 338-7300

Name : Steve McAdams
Location : Ramsey Property, Holt 1
NE Corner

Lab ID No.: : 761596
Customer Code : 70
Sample No. : 5632
Received : 3/27/2015
Report Date : 4/8/2015

received 04/13/2015
Location 433758
API 009-06676
Document 2142843

TEST RESULTS

Texture Class	Sand (%)	Silt (%)	Clay (%)
Loamy Sand	83.8	3.8	12.5

Signature



Soil, Water & Forage Analytical Laboratory

Oklahoma State University Division of Agricultural Sciences and Natural Resources
045 Agricultural Hall
Stillwater, OK 74078
E-mail: soiltesting@okstate.edu
Website: www.soiltesting.okstate.edu

SOIL TEXTURE REPORT

TEXAS CO EXT OFC
PO BOX 320
301 N MAIN
GUYMON, OK 73942
(580) 338-7300

Name : Steve McAdams
Location : Ramsey Properties, Holt 1
SE Coner

Lab ID No.: : 761595
Customer Code : 70
Sample No. : 5631
Received : 3/27/2015
Report Date : 4/8/2015

TEST RESULTS

Texture Class	Sand (%)	Silt (%)	Clay (%)
Sandy Loam	81.2	6.2	12.5

Signature



Soil, Water & Forage Analytical Laboratory

Oklahoma State University Division of Agricultural Sciences and Natural Resources
045 Agricultural Hall
Stillwater, OK 74078
E-mail: soiltesting@okstate.edu
Website: www.soiltesting.okstate.edu

SOIL TEXTURE REPORT

TEXAS CO EXT OFC
PO BOX 320
301 N MAIN
GUYMON, OK 73942
(580) 338-7300

Name : Steve McAdams
Location : Ramsey Property, Holt 1
NW Corner

Lab ID No.: : 761594
Customer Code : 70
Sample No. : 5630
Received : 3/27/2015
Report Date : 4/8/2015

TEST RESULTS

Texture Class	Sand (%)	Silt (%)	Clay (%)
Loamy Sand	82.5	6.2	11.2

Signature



Soil, Water & Forage Analytical Laboratory

Oklahoma State University Division of Agricultural Sciences and Natural Resources
045 Agricultural Hall
Stillwater, OK 74078
E-mail: soiltesting@okstate.edu
Website: www.soiltesting.okstate.edu

SOIL TEXTURE REPORT

TEXAS CO EXT OFC
PO BOX 320
301 N MAIN
GUYMON, OK 73942
(580) 338-7300

Name : Steve McAdams
Location : Ramsey Property, Holt 1
SW Corner

Lab ID No.: : 761593
Customer Code : 70
Sample No. : 5629
Received : 3/27/2015
Report Date : 4/8/2015

TEST RESULTS

Texture Class	Sand (%)	Silt (%)	Clay (%)
Sandy Loam	78.8	7.5	13.8

Signature