



photo 1: Facing north along the access road to the location.



photo 2: Facing northeast towards the location from the access road.



photo 3: Center of the location facing North.



photo 4: Center of the location facing West.



photo 5: Center of the location facing South.



photo 6: Center of the location facing East.



photo 7: Weed growth (kochia, russian thistle) throughout the site.



photo 8: Weed growth (kochia, russian thistle) throughout the site.