



photo 1: Well sign, Mahalo #11.



photo 2: Facing south towards the location.



photo 3: Center of the location facing North.



photo 4: Center of the location facing West.



photo 5: Center of the location facing South.



photo 6: Center of the location facing East.



photo 7: Weed growth (russian thistle) throughout the site.



photo 8: Fence around the location is down at several places. Weed debris in fence.