

**FORM
INSP**Rev
05/11

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


DE	ET	OE	ES
----	----	----	----

 Inspection Date:
04/16/2015

 Document Number:
666800881

 Overall Inspection:
SATISFACTORY
FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	265896	334622	Murray, Richard	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED
☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Compliance Summary:QtrQtr: NWNW Sec: 14 Twp: 7S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/11/2005	200067656	PR	PR	SATISFACTORY		Pass	No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
265888	WELL	PR	07/26/2003	GW	045-09081	ROSE RANCH 14-4 (D14)	PR	<input checked="" type="checkbox"/>
265889	WELL	PR	07/26/2003	GW	045-09080	ROSE RANCH 15-7A (D14)	PR	<input checked="" type="checkbox"/>
265891	WELL	PR	07/27/2003	GW	045-09088	ROSE RANCH 14-3C (D14)	PR	<input checked="" type="checkbox"/>
265892	WELL	PR	08/20/2003	GW	045-09087	ROSE RANCH 14-6B (D14)	PR	<input checked="" type="checkbox"/>
265893	WELL	SI	12/18/2013	GW	045-09086	ROSE RANCH 15-8 (D14)	SI	<input checked="" type="checkbox"/>
265895	WELL	PR	07/24/2003	GW	045-09084	ROSE RANCH 11-13 (D14)	PR	<input checked="" type="checkbox"/>
265896	WELL	PR	08/10/2003	GW	045-09083	ROSE RANCH 14-5B (D14)	PR	<input checked="" type="checkbox"/>
267639	WELL	PR	08/25/2003	GW	045-09207	ROSE RANCH 10-16D (D14)	PR	<input checked="" type="checkbox"/>
272391	WELL	AL	10/19/2006	LO	045-10072	ROSE RANCH 14-4C (D14)	AL	<input checked="" type="checkbox"/>
272392	WELL	AL	02/18/2005	LO	045-10071	ROSE RANCH 15-2A (D14)	AL	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

272408	WELL	PR	05/23/2005	GW	045-10081	ROSE RANCH 11-14A (D14)	PR	<input checked="" type="checkbox"/>
272409	WELL	PR	01/14/2006	GW	045-10080	ROSE RANCH 14-4A (D14)	PR	<input checked="" type="checkbox"/>
272410	WELL	AL	10/12/2006	LO	045-10079	ROSE RANCH 14-5A (D14)	AL	<input checked="" type="checkbox"/>
276284	WELL	PR	05/07/2005	GW	045-10438	ROSE RANCH 14-3D (D14W)	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Vertical Heated Separator	11	SATISFACTORY			
Gas Meter Run	1	SATISFACTORY			
Plunger Lift	11	SATISFACTORY			

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 265896

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 265888 Type: WELL API Number: 045-09081 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 265889 Type: WELL API Number: 045-09080 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 265891 Type: WELL API Number: 045-09088 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 265892	Type: WELL	API Number: 045-09087	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				

Facility ID: 265893	Type: WELL	API Number: 045-09086	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
S/A/V: SATISFACTORY CA Date: _____				
CA: _____				
Comment: Form 4 on file to TA				

Facility ID: 265895	Type: WELL	API Number: 045-09084	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				

Facility ID: 265896	Type: WELL	API Number: 045-09083	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				

Facility ID: 267639	Type: WELL	API Number: 045-09207	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				

Facility ID: 272391	Type: WELL	API Number: 045-10072	Status: AL	Insp. Status: AL
Idle Well				
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
S/A/V: _____ CA Date: _____				
CA: _____				
Comment: No visal sign of well				

Facility ID: 272392	Type: WELL	API Number: 045-10071	Status: AL	Insp. Status: AL
Idle Well				
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
S/A/V: _____ CA Date: _____				
CA: _____				
Comment: No visal sign of well				

Facility ID: 272408	Type: WELL	API Number: 045-10081	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				

Facility ID: 272409	Type: WELL	API Number: 045-10080	Status: PR	Insp. Status: PR
Producing Well				
Comment: Plunger lift				

Facility ID: 272410 Type: WELL API Number: 045-10079 Status: AL Insp. Status: AL

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: No visal sign of well

Facility ID: 276284 Type: WELL API Number: 045-10438 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? ☐ Pass ☐ CM _____

CA _____ CA Date _____

Waste Material Onsite? ☐ Pass ☐ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? ☐ Pass ☐ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? ☐ Pass ☐ CM _____

CA _____ CA Date _____

Inspector Name: Murray, Richard

Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? Pass CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Culverts	Pass			
Blankets	Pass					

Inspector Name: Murray, Richard

Berms	Pass				
		Ditches	Pass		
		Sediment Traps	Pass		
Rip Rap	Pass				

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT