

**FORM
INSP**Rev
05/11

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/20/2015

Document Number:

668402860

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>289567</u>	<u>311685</u>	<u>BROWNING, CHUCK</u>	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10071Name of Operator: BARRETT CORPORATION* BILLAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED
☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Rants, John	970-319-0013	jrants@vnrllc.com	Production Foreman

Compliance Summary:

QtrQtr:	<u>NENW</u>	Sec:	<u>31</u>	Twp:	<u>6S</u>	Range:	<u>91W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/23/2014	668402622	SI	SI	SATISFACTORY	P		No
07/30/2014	668402485	SI	SI	SATISFACTORY	P		No
02/10/2014	670201248	SI	AC	SATISFACTORY			No
01/16/2013	663800694	SI	AC	SATISFACTORY			No
09/10/2012	663800489	SI	SI	SATISFACTORY			No
08/29/2012	663800484	SI	SI	ALLEGED VIOLATION	I		Yes
07/22/2011	200316611	RT	AC	SATISFACTORY			No
08/13/2010	200266715	RT	AC	SATISFACTORY			No
08/12/2009	200217305	RT	SI	SATISFACTORY			No
08/25/2007	200121376	MI	AC	SATISFACTORY			No
04/22/2007	200109497	MI	SI	SATISFACTORY		Pass	No

Inspector Comment:UIC - Routine inspection.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
159176	UIC DISPOSAL	AC	05/01/2007		-	GGU RODREICK	AC	<input checked="" type="checkbox"/>
211492	WELL	PR	08/08/2000	GW	045-07252	GIBSON GULCH UNIT 3 -31 B	PR	<input type="checkbox"/>
289567	WELL	IJ	12/09/2014	DSPW	045-13803	GGU RODREICK 21B-31-691 SWD	AC	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			
Main	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Venting:**

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 289567

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 159176 Type: UIC API Number: - Status: AC Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: 2880

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) _____ Inj Zone: _____

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: _____

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: **UIC - Routine inspection. Active Injection at time of inspection.**

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Facility ID: 289567 Type: WELL API Number: 045-13803 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 2246 _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) _____ Inj Zone: CZ-CR

TC: Pressure or inches of Hg 1444 _____ Previous Test Pressure _____ Last MIT: 12/23/2014

Brhd: Pressure or inches of Hg 0 _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: **UIC - Routine inspection. Active injection. Personel onsite.
 No monthly production/injection report since 11/2014**

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation _____ Pass _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Inspector Name: BROWNING, CHUCK

Access Roads	Regraded _____	Contoured _____	Culverts removed _____
	Gravel removed _____		
Location and associated production facilities reclaimed _____		Locations, facilities, roads, recontoured _____	
Compaction alleviation _____	Dust and erosion control _____		
Non cropland: Revegetated 80% _____		Cropland: perennial forage _____	
Weeds present _____	Subsidence _____		
Comment: _____			
Corrective Action: _____			Date _____
Overall Final Reclamation _____		Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	MHSP	Pass	

S/A/V: SATISFACTOR
Y _____ Corrective Date: _____

Comment: _____
CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668402860	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3593763