

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/21/2015

Document Number:

674102229

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	437832	437829	Rickard, Jeff	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 20203 HIGHWAY 60City: PLATTEVILLE State: CO Zip: 80651

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Sandquist, Rhonda	970-737-1073	rsandquist@syrinfo.com	
Pennington, Dave		dpennington@syrinfo.com	Synergy Inspection
Rasmuson, Craig	970-737-1093	craigasmuson@comcast.net	Production supervisor

**Compliance Summary:**QtrQtr: SWSE Sec: 4 Twp: 4N Range: 68W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
437823	WELL	DG	07/06/2014		123-39711	SRC KIEHN 22-4CHZ	WK	<input checked="" type="checkbox"/>
437824	WELL	DG	07/06/2014		123-39712	SRC KIEHN 32-4NHZ	WK	<input checked="" type="checkbox"/>
437825	WELL	DG	07/06/2014		123-39713	SRC KIEHN 32-4CHZ	WK	<input checked="" type="checkbox"/>
437826	WELL	DG	10/20/2014		123-39714	SRC Weis K-9NHZ	WK	<input checked="" type="checkbox"/>
437827	WELL	DG	07/06/2014		123-39715	SRC KIEHN C-4NHZ	WK	<input checked="" type="checkbox"/>
437828	WELL	DG	07/06/2014		123-39716	SRC KIEHN N-4NHZ	WK	<input checked="" type="checkbox"/>
437830	WELL	DG	10/20/2014		123-39717	SRC Weis 12-9NHZ	WK	<input checked="" type="checkbox"/>
437831	WELL	DG	07/06/2014		123-39718	SRC KIEHN C-4CHZ	WK	<input checked="" type="checkbox"/>
437832	WELL	DG	07/06/2014		123-39719	SRC KIEHN 31-4CHZ	WK	<input checked="" type="checkbox"/>
437833	WELL	DG	10/20/2014		123-39720	SRC Weis 12-9CHZ	WK	<input checked="" type="checkbox"/>
437834	WELL	DG	07/06/2014		123-39721	SRC KIEHN 31-4NHZ	WK	<input checked="" type="checkbox"/>
437835	WELL	DG	10/20/2014		123-39722	SRC Weis A-9CHZ	WK	<input checked="" type="checkbox"/>
437881	WELL	DG	10/20/2014		123-39746	SRC Weis A-9NHZ	WK	<input checked="" type="checkbox"/>

**Equipment:****Location Inventory**

Inspector Name: Rickard, Jeff

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>13</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>4</u>	Separators: <u>13</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>6</u>	Oil Tanks: <u>22</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

Emergency Contact Number (S/A/V): \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

### Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

### Venting:

Yes/No	Comment

### Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

### Predrill

Location ID: 437832

### Site Preparation:

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/A/V: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

### Form 2A COAs:

S/A/V: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

### Wildlife BMPs:

BMP Type	Comment
Noise mitigation	Noise. The drilling site is far enough away from the building unit that noise mitigation is not required.
General Housekeeping	Fencing requirements. A meeting with the surface owner will determine fencing plan.
General Housekeeping	Removal of surface trash. All trash, debris and material not intrinsic to the operation of the oil and gas facility shall be removed and legally disposed of as applicable.
Planning	Multi-well Pads. It is a multi-well pad located in a manner which allows for resource extraction while maintaining the highest distances possible from the offsetting residential areas and complies with the wishes of the surface owner.
Drilling/Completion Operations	Guy line anchors. All guy line anchors shall be brightly marked pursuant to Rule 604.c(2)Q.

Emissions mitigation	Green Completions – Emission Control Systems. Test separators and associated flow lines and sand traps shall be installed on-site to accommodate Green completions techniques pursuant to COGCC Rules. In the anticipated absence of a viable gas sales line, the flowback gas shall be thermally oxidized in an emissions control device (ECD), which will be installed and kept in operable condition for least the first 90-days of production pursuant to CDPHE rules. This ECD shall have an adequate capacity for 1.5 times the largest flowback within a 10 mile radius, will be flanged to route gas to other or permanent oxidizing equipment and shall be provided with the equipment needed to maintain combustion where non-combustible gases are present.
Construction	Berm construction. Tank berms shall be constructed of steel rings with a synthetic or engineered liner and designed to contain 150% of the capacity of the largest tank. All berms will be visually checked periodically to ensure proper working condition.
Drilling/Completion Operations	Closed Loop Drilling Systems – Pit Restrictions. Not applicable; a closed-loop system will be used for drilling.
Material Handling and Spill Prevention	Loadlines. All loadlines shall be bullplugged or capped.
Planning	Development from existing well pads. These additional wells are located on an already approved location assessment and have been clustered in two lines to minimize surface disturbance area and cut and fill volumes.
Material Handling and Spill Prevention	Tank specifications. Tanks will be designed, constructed and maintained in accordance with NFPA Code 30. The tanks are visually inspected once a day for issues, and recorded inspections are conducted once a month.
Drilling/Completion Operations	BOPE for well servicing operations. Adequate BOP equipment shall be used. Stabbing valves shall be installed in the event of reverse circulation and shall be prior tested with low and high pressure fluid.
Planning	Site-specific measures. This location has been designed to mitigate the visual impacts to the surrounding properties.
Drilling/Completion Operations	Blowout preventer equipment (“BOPE”). A double ram and annular preventer will be used during drilling. At least the drilling company shall have a valid well blowout prevention certifications.
Material Handling and Spill Prevention	Leak Detection Plan. Pumper will visit the location daily and visually inspect all tanks and fittings for leaks. Additionally, monthly documented SPCCP inspections are conducted pursuant to 40 CFR §112.
Drilling/Completion Operations	Anti-Collision BMP: Prior to drilling operations, Operator will perform an anti-collision scan of existing offset wells that have the potential of being within close proximity of the proposed wells. This anti-collision scan will include definitive MWD or gyro surveys of the offset wells with included error of uncertainty per survey instrument, and compared against the proposed wellpath with its respective error of uncertainty. If current surveys do not exist for the offset wells, Operator may have gyro surveys conducted to verify bottomhole location. The proposed well will only be drilled if the anti-collision scan results indicate that there is not a risk for collision, or harm to people or the environment. For the proposed well, upon conclusion of drilling operations, an as constructed gyro survey will be submitted to COGCC with the Form 5.
Traffic control	Access roads. The access road will be constructed to accommodate local emergency vehicles. This road will be maintained for access at all times.
Drilling/Completion Operations	Drill stem tests. Not applicable; no Drill Stem tests are planned.
Drilling/Completion Operations	Pit level indicators. Not applicable; a closed-loop system will be used and no pits shall be dug.
Traffic control	Traffic Plan. Traffic will be routed to minimize local interruption.
Final Reclamation	Identification of plugged and abandoned wells. P&A'd wells shall be identified pursuant to 319.a. (5).
Drilling/Completion Operations	Bradenhead Monitoring BMP: Operator will comply with COGCC Policy for Bradenhead Monitoring During Hydraulic Fracturing Treatments in the Greater Wattenberg Area dated May 29, 2012.
Drilling/Completion Operations	Control of fire hazards. All materials which are considered fire hazards shall be a minimum of 25' from the wellhead tanks or separators. Electrical equipment shall comply with API RP 500 and will comply with the current national electrical code.
Final Reclamation	Well site cleared. Within 90-day subsequent to the time of plugging and abandonment of the entire site, superfluous debris and equipment shall be removed from the site

Inspector Name: Rickard, Jeff

<b>S/AV:</b> _____	<b>Comment:</b> _____
<b>CA:</b> _____	<b>Date:</b> _____
<b>Stormwater:</b>	
<b>Comment:</b> _____	
<b>Staking:</b>	
<b>On Site Inspection (305):</b>	
<b>Surface Owner Contact Information:</b>	
Name: _____	Address: _____
Phone Number: _____	Cell Phone: _____
<b>Operator Rep. Contact Information:</b>	
Landman Name: _____	Phone Number: _____
Date Onsite Request Received: _____	Date of Rule 306 Consultation: _____
Request LGD Attendance: _____	
<b>LGD Contact Information:</b>	
Name: _____	Phone Number: _____
Agreed to Attend: _____	
<b>Summary of Landowner Issues:</b>	
_____	
<b>Summary of Operator Response to Landowner Issues:</b>	
_____	
<b>Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:</b>	
_____	

**Facility**

Facility ID: 437823	Type: WELL	API Number: 123-39711	Status: DG	Insp. Status: WK
---------------------	------------	-----------------------	------------	------------------

**Workover**

Comment: Awating drill out or has been drilled out.

Facility ID: 437824	Type: WELL	API Number: 123-39712	Status: DG	Insp. Status: WK
---------------------	------------	-----------------------	------------	------------------

**Workover**

Comment: Awating drill out or has been drilled out.

Facility ID: 437825	Type: WELL	API Number: 123-39713	Status: DG	Insp. Status: WK
---------------------	------------	-----------------------	------------	------------------

**Workover**

Comment: Awating drill out or has been drilled out.

Facility ID: 437826	Type: WELL	API Number: 123-39714	Status: DG	Insp. Status: WK
---------------------	------------	-----------------------	------------	------------------

**Workover**

Comment: Awating drill out or has been drilled out.

Facility ID: 437827	Type: WELL	API Number: 123-39715	Status: DG	Insp. Status: WK
---------------------	------------	-----------------------	------------	------------------

**Workover**

Comment: Awating drill out or has been drilled out.

Facility ID: 437828	Type: WELL	API Number: 123-39716	Status: DG	Insp. Status: WK
---------------------	------------	-----------------------	------------	------------------

**Workover**Comment: Awating drill out or has been drilled out.Facility ID: 437830 Type: WELL API Number: 123-39717 Status: DG Insp. Status: WK**Workover**Comment: Awating drill out or has been drilled out.Facility ID: 437831 Type: WELL API Number: 123-39718 Status: DG Insp. Status: WK**Workover**Comment: Awating drill out or has been drilled out.Facility ID: 437832 Type: WELL API Number: 123-39719 Status: DG Insp. Status: WK**Workover**Comment: Awating drill out or has been drilled out.Facility ID: 437833 Type: WELL API Number: 123-39720 Status: DG Insp. Status: WK**Workover**Comment: Awating drill out or has been drilled out.Facility ID: 437834 Type: WELL API Number: 123-39721 Status: DG Insp. Status: WK**Workover**Comment: Drill out.Facility ID: 437835 Type: WELL API Number: 123-39722 Status: DG Insp. Status: WK**Workover**Comment: Awating drill out or has been drilled out.Facility ID: 437881 Type: WELL API Number: 123-39746 Status: DG Insp. Status: WK**Workover**Comment: Awating drill out or has been drilled out.**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Inspector Name: Rickard, Jeff

Emission Control Burner (ECB): Y \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: OFF \_\_\_\_\_ Wildlife Protection Devices (fired vessels): YES \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: IRRIGATED

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? In \_\_\_\_\_ Production areas stabilized ? In \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IRRIGATED

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Rickard, Jeff

Well plugged _____	Pit mouse/rat holes, cellars backfilled _____		
Debris removed _____	No disturbance /Location never built _____		
Access Roads _____	Regraded _____	Contoured _____	Culverts removed _____
Gravel removed _____			
Location and associated production facilities reclaimed _____		Locations, facilities, roads, recontoured _____	
Compaction alleviation _____		Dust and erosion control _____	
Non cropland: Revegetated 80% _____		Cropland: perennial forage _____	
Weeds present _____		Subsidence _____	
Comment: _____			
Corrective Action: _____			Date _____
Overall Final Reclamation _____		Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Waddles	Pass					

S/A/V: SATISFACTOR  
Y \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT