



Photo 1. View of western edge of project area from northwestern corner facing southward.



Photo 2. View of southern edge of project area from southwestern corner facing eastward. Straw wattles and cobble outlet can be seen.



Photo 3. View of culvert outlet near entrance to well pad. Straw wattles and cobble armoring can be seen.



Photo 4. View of well pad drainage along outer edge of working area from southwestern corner facing northward.



Photo 5. View of northern edge of project area from northeastern corner facing westward.