

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/27/2015

Document Number:

675201499

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	286066	334682	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Compliance Summary:QtrQtr: SES Sec: 20 Twp: 7S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/21/2013	663800782	PR	PR	SATISFACTORY	I		No
02/21/2013	663800781			SATISFACTORY			No
09/08/2008	200195791	PR	PR	SATISFACTORY			No
04/14/2008	200130580	PR	PR	SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
286066	WELL	PR	01/17/2007	GW	045-12603	FEDERAL 20-10 (PN20)	PR	<input checked="" type="checkbox"/>
286631	WELL	PR	01/07/2007	GW	045-12713	FEDERAL 20-12(PN20)	PR	<input checked="" type="checkbox"/>
413026	WELL	PR	07/12/2011	GW	045-18708	Federal 20-11 (PN20)	PR	<input checked="" type="checkbox"/>
413027	WELL	AL	10/17/2012	LO	045-18709	Federal 20-14 (PN20)	AL	<input type="checkbox"/>
413028	WELL	AL	10/17/2012	LO	045-18710	Federal 20-11BB (PN20)	AL	<input type="checkbox"/>
413029	WELL	PR	07/12/2011	GW	045-18711	Federal 20-14BB (PN20)	PR	<input checked="" type="checkbox"/>
415750	WELL	PR	07/12/2011	GW	045-19158	Federal Gardner 20-7 (PN20)	PR	<input checked="" type="checkbox"/>
415795	WELL	PR	07/12/2011	GW	045-19163	Federal Gardner 20-7BB (PN20)	PR	<input checked="" type="checkbox"/>

Inspector Name: CONKLIN, CURTIS

415799	WELL	PR	07/12/2011	GW	045-19164	Federal Gardner 20-6 (PN20)	PR	<input checked="" type="checkbox"/>
416168	WELL	AL	05/24/2012	LO	045-19226	Federal Gardner 20-6BB	AL	<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>10</u>	Production Pits: _____
Condensate Tanks: <u>10</u>	Water Tanks: <u>1</u>	Separators: <u>10</u>	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: <u>1</u>	Flare: <u>1</u>	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: 970-285-2600

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
LOCATION	SATISFACTORY	<u>Wire fence</u>		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Bird Protectors	3	SATISFACTORY			
Plunger Lift	7	SATISFACTORY			
Horizontal Heated Separator	2	SATISFACTORY			
Gas Meter Run	1	SATISFACTORY			
Vertical Heated Separator	5	SATISFACTORY			

Facilities:☐ New Tank

Tank ID: _____

Inspector Name: CONKLIN, CURTIS

Contents	#	Capacity	Type	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST	,
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment	Same			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST	,
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 286066

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Agency	kubeczko	Operator must implement best management practices to contain any unintentional release of fluids.	02/04/2010
Agency	kubeczko	Location is in a sensitive area because of close surface water; therefore, operator must ensure 110 percent secondary containment for any volume of fluids contained at tank pad site during operations.	02/04/2010

S/A/V: _____ **Comment:** Secondary containment in place around fluids.**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 286066 Type: WELL API Number: 045-12603 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 286631 Type: WELL API Number: 045-12713 Status: PR Insp. Status: PR

Producing WellComment: **PR w/ plunger**Facility ID: 413026 Type: WELL API Number: 045-18708 Status: PR Insp. Status: PR**Producing Well**Comment: **PR w/ plunger**Facility ID: 413029 Type: WELL API Number: 045-18711 Status: PR Insp. Status: PR**Producing Well**Comment: **PR w/ plunger**Facility ID: 415750 Type: WELL API Number: 045-19158 Status: PR Insp. Status: PR**Producing Well**Comment: **PR w/ plunger**Facility ID: 415795 Type: WELL API Number: 045-19163 Status: PR Insp. Status: PR**Producing Well**Comment: **PR w/ plunger**Facility ID: 415799 Type: WELL API Number: 045-19164 Status: PR Insp. Status: PR**Producing Well**Comment: **PR w/ plunger****Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment:

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: **Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Inspector Name: CONKLIN, CURTIS

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Retention Ponds	Pass					
Berms	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Seeding	Pass					

S/A/V: SATISFACTOR _____ Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT