

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/27/2015

Document Number:

675201501

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334405	334405	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 600 17TH STREET #1600NCity: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Elsener, Garrett		garrett@caerusoilandgas.com	
Janicek, Jake		JJanicek@caerusoilandgas.com	

Compliance Summary:QtrQtr: SWSE Sec: 26 Twp: 7S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/07/2014	675200637			SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
159318	UIC DISPOSAL	AC	10/07/2009		-	PARACHUTE RANCH 26-34B	AC	<input type="checkbox"/>
295170	WELL	PR	01/29/2010	GW	045-15681	PARACHUTE RANCH 26-34C	PR	<input checked="" type="checkbox"/>
295171	WELL	PR	12/01/2009	GW	045-15682	PARACHUTE RANCH 26-24A	PR	<input checked="" type="checkbox"/>
295172	WELL	PR	02/04/2010	GW	045-15683	PARACHUTE RANCH 26-24B	PR	<input checked="" type="checkbox"/>
295173	WELL	PR	11/30/2009	GW	045-15684	PARACHUTE RANCH 26-34A	PR	<input checked="" type="checkbox"/>
295174	WELL	PR	01/10/2010	GW	045-15685	PARACHUTE RANCH 26-44B	PR	<input checked="" type="checkbox"/>
295175	WELL	PR	12/14/2009	GW	045-15686	PARACHUTE RANCH 26-44A	PR	<input checked="" type="checkbox"/>
295176	WELL	PR	01/29/2010	GW	045-15687	PARACHUTE RANCH 26-44D	PR	<input checked="" type="checkbox"/>
295177	WELL	PR	12/27/2009	GW	045-15688	PARACHUTE RANCH 26-34D	PR	<input checked="" type="checkbox"/>

Inspector Name: CONKLIN, CURTIS

295178	WELL	IJ	06/27/2011	GW	045-15689	PARACHUTE RANCH 26-34B	IJ	<input type="checkbox"/>
295179	WELL	PR	12/16/2009	GW	045-15690	PARACHUTE RANCH 26-24C	PR	<input checked="" type="checkbox"/>
295180	WELL	PR	12/24/2009	GW	045-15691	PARACHUTE RANCH 26-24D	PR	<input checked="" type="checkbox"/>
295181	WELL	PR	01/11/2010	GW	045-15692	PARACHUTE RANCH 26-44C	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	12	SATISFACTORY			
Bird Protectors	6	SATISFACTORY			
Plunger Lift	11	SATISFACTORY			

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	6	300 BBLS	STEEL AST	,

Inspector Name: CONKLIN, CURTIS

S/A/V:	SATISFACTORY	Comment:				
Corrective Action:					Corrective Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Corrective Action					Corrective Date	
Comment						

<u>Venting:</u>			
Yes/No	Comment		
NO			

<u>Flaring:</u>					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

Predrill

Location ID: 334405

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 295170 Type: WELL API Number: 045-15681 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295171 Type: WELL API Number: 045-15682 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295172 Type: WELL API Number: 045-15683 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295173 Type: WELL API Number: 045-15684 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295174 Type: WELL API Number: 045-15685 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295175 Type: WELL API Number: 045-15686 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295176 Type: WELL API Number: 045-15687 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295177 Type: WELL API Number: 045-15688 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295179 Type: WELL API Number: 045-15690 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295180 Type: WELL API Number: 045-15691 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 295181 Type: WELL API Number: 045-15692 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Inspector Name: CONKLIN, CURTIS

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Inspector Name: CONKLIN, CURTIS

Reminder:

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
Debris removed _____ No disturbance /Location never built _____
Access Roads Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____

Comment:

Corrective Action:

Date

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Check Dams	Pass			
Berms	Pass	Gravel	Pass			
Drains	Pass	Compaction	Pass			

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT