



photo 1: Access road northwest to the location.



photo 2: Access road northwest to the location.



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.



photo 7: Beginning of the vegetation transect conducted on the location facing northwest.



photo 8: End of the vegetation transect conducted on the location facing southeast.




photo 9: Beginning of the vegetation transect conducted off the location facing northeast.



photo 10: End of the vegetation transect conducted off the location facing southeast.



photo 11: Weed growth (Western tansymustard) growing on the location and access road.



photo 12: Weed growth (Redstem filaree) growing on the location and access road.