



**photo 1:** Facing northwest towards the location along the access road.



**photo 2:** Facing west towards the location.





**photo 3:** Center of the location facing north.



**photo 4:** Center of the location facing west.





**photo 5:** Center of the location facing south.



**photo 6:** Center of the location facing east.





**photo 7:** Northwest corner of the location facing southeast.



**photo 8:** South side of the location facing northwest.





**photo 9:** Berm around the south side of the location.



**photo 10:** Straw wattle remains at the east side of the location.





**photo 11:** Weed growth (common mullein) growing on the location.



**photo 12:** Weed growth (thistle) growing on the location.