

Wolf Mountain 15-2-7-87

Inspection# 673402069

Stained soil from release of
E&P waste. (Jeep to illustrate
scale of release)



Stained soil from release of
E&P waste with some free
standing fluid still present.
Vehicle tracking of release
visible to left of affected
area.



Pool of hydrocarbon stained fluid in foreground with larger release still visible in background.



E&P waste release adjacent to tank battery. Evidence of vehicle tracking, exiting release on right side.



Location overview. Visible:
stained soil patches from E&P
release, equipment storage,
lack of stormwater BMPs.



Location overview to
illustrate proximity and grade
relation between stored
materials, E&P release and
stock/wildlife pond.



Only sign with on location.
Ommix is no longer the
operator.

