

WPX Energy

Location # 335996

AP-66S95W8NENW

Washing and erosion of road ditch.



Washing of cut ditch to check dam.



Erosion around outside of check dam
where storm water bypassed dam.

