

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:  
04/28/2015Document Number:  
674701337Overall Inspection:  
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335996	335996	LONGWORTH, MIKE	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, WPX	970-263-2716	COGCCInspectionReports@wpxenergy.com	WPX Inspection Mail Box

**Compliance Summary:**QtrQtr: NENW Sec: 18 Twp: 6S Range: 95W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
159566	SPILL OR RELEASE	CL	01/08/2015		-	SPILL/RELEASE POINT	CL	<input type="checkbox"/>
285452	WELL	AL	11/06/2013	LO	045-12482	AP 21-18-695	AL	<input type="checkbox"/>
290248	WELL	PR	04/18/2007	GW	045-14065	AP 421-18-695	PR	<input checked="" type="checkbox"/>
290249	WELL	PR	04/18/2007	GW	045-14064	AP 521-18-695	PR	<input checked="" type="checkbox"/>
297290	WELL	XX	07/22/2008	LO	045-16379	AP 11-18-695	ND	<input type="checkbox"/>
297291	WELL	XX	07/22/2008	LO	045-16380	AP 12-18-695	ND	<input type="checkbox"/>
297292	WELL	XX	07/22/2008	LO	045-16381	AP 14-7-695	ND	<input type="checkbox"/>
298107	WELL	PR	09/04/2008	GW	045-17073	AP 321-18-695	PR	<input checked="" type="checkbox"/>
298108	WELL	PR	06/24/2010	GW	045-17074	AP 322-18-695	PR	<input checked="" type="checkbox"/>
298109	WELL	PR	08/20/2009	GW	045-17075	AP 522-18-695	PR	<input checked="" type="checkbox"/>
298110	WELL	XX	09/04/2008	LO	045-17076	AP 412-18-695	ND	<input type="checkbox"/>
298111	WELL	PR	06/24/2010	GW	045-17077	AP 531-18-695	PR	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

298112	WELL	PR	06/24/2010	GW	045-17078	AP 331-18-695	PR	<input checked="" type="checkbox"/>
298113	WELL	XX	09/04/2008	LO	045-17079	AP 411-18-695	ND	<input type="checkbox"/>
298114	WELL	PR	11/01/2011	GW	045-17080	AP 332-18-695	PR	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: \_\_\_\_\_ Drilling Pits: \_\_\_\_\_ Wells: \_\_\_\_\_ Production Pits: \_\_\_\_\_  
 Condensate Tanks: \_\_\_\_\_ Water Tanks: \_\_\_\_\_ Separators: \_\_\_\_\_ Electric Motors: \_\_\_\_\_  
 Gas or Diesel Mortors: \_\_\_\_\_ Cavity Pumps: \_\_\_\_\_ LACT Unit: \_\_\_\_\_ Pump Jacks: \_\_\_\_\_  
 Electric Generators: \_\_\_\_\_ Gas Pipeline: \_\_\_\_\_ Oil Pipeline: \_\_\_\_\_ Water Pipeline: \_\_\_\_\_  
 Gas Compressors: \_\_\_\_\_ VOC Combustor: \_\_\_\_\_ Oil Tanks: \_\_\_\_\_ Dehydrator Units: \_\_\_\_\_  
 Multi-Well Pits: \_\_\_\_\_ Pigging Station: \_\_\_\_\_ Flare: \_\_\_\_\_ Fuel Tanks: \_\_\_\_\_

**Location****Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: 970-285-9377

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
SEPARATOR	SATISFACTORY			
TANK BATTERY	SATISFACTORY			

**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	2	SATISFACTORY	Chemical containers at wells		

**Facilities:**☐ New Tank

Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
METHANOL	1	<50 BBLS	STEEL AST	,

S/A/V: SATISFACTORY Comment: \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition		Adequate			
Other (Content) _____					
Other (Capacity) 500 gallons					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
<b>Facilities:</b> <input type="checkbox"/> New Tank      Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	2	400 BBLS	HEATED STEEL AST	,	
S/A/V:	SATISFACTORY		Comment: <span style="color:red">Airs id 045-2039-001</span>		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition		Adequate			
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Corrective Action				Corrective Date	
Comment					
<b>Facilities:</b> <input type="checkbox"/> New Tank      Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	2	400 BBLS	HEATED STEEL AST	39.530040,-108.041600	
S/A/V:	SATISFACTORY		Comment: <span style="color:red">Airs id 045-2039-002</span>		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition		Adequate			
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					

<b>Venting:</b>	
Yes/No	Comment
YES	Bradens open to vent.

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335996

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 290248 Type: WELL API Number: 045-14065 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Inspector Name: LONGWORTH, MIKE

Facility ID: 290249 Type: WELL API Number: 045-14064 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 298107 Type: WELL API Number: 045-17073 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 298108 Type: WELL API Number: 045-17074 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 298109 Type: WELL API Number: 045-17075 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 298111 Type: WELL API Number: 045-17077 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 298112 Type: WELL API Number: 045-17078 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 298114 Type: WELL API Number: 045-17080 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

**Environmental**

**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

Lat Long

DWR Receipt Num: Owner Name: GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams	Fail			
				MHSP	Pass	
Ditches	Pass					
		Ditches	Fail			
Check Dams	Pass					
Seeding						
		Culverts	Pass			

S/A/V: **ACTION REQUIRED** Corrective Date: **05/30/2015**

Comment: Road ditch on down grade access road into location is washing and moving sediment. Storm water flow over ran the shallow cut ditch to the check dam. Erosion around the outside of check dam where storm waters bypassed the check dam inlet.

CA: Repair and maintain BMPs.

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674701351	Storm water bmps	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3600493">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3600493</a>