



photo 1: Facing east along the access road towards the location.



photo 2: West side of the location facing east. Area bare of vegetation approx. 120'x60'.



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.



photo 7: North side of the location facing north. Areas bare of vegetation approx. 80'x40'.



photo 8: North side of the location facing south.



photo 9: Pipe riser at center of location. Lat/Long:37.95993,-102.50062.



photo 10: Pipe riser at center of location. Lat/Long:37.95993,-102.50062.