

Inspector Name: Sherman, Susan

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:  
05/01/2015Document Number:  
673710314Overall Inspection:  
SATISFACTORY**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 209467      | 322167 | Sherman, Susan  | <input type="checkbox"/> |             |

**Operator Information:**

OGCC Operator Number: 74165

Name of Operator: RENEGADE OIL & GAS COMPANY LLC

Address: 6155 S MAIN STREET #210

City: AURORA State: CO Zip: 80016

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name   | Phone          | Email                     | Comment          |
|----------------|----------------|---------------------------|------------------|
| Ikenouye, Teri |                | teri.ikenouye@state.co.us | COGCC Production |
| Condill, J.B.  | (303) 680-4725 | jbcrog@aol.com            | All Inspections  |
| Ingve, Ed      | (303) 680-4725 | ed@renegadeoilandgas.com  | All Inspections  |
| Espinosa, Bill | (303) 829-4982 | billespinosa30@yahoo.com  |                  |

**Compliance Summary:**QtrQtr: SENW Sec: 7 Twp: 6S Range: 62W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 03/20/2014 | 673701787 | PR         | PR          | ACTION REQUIRED               | P        |                | No              |
| 05/10/2012 | 664000575 | PR         | PR          | SATISFACTORY                  | P        |                | No              |
| 09/22/2010 | 200281709 | SR         | PR          | SATISFACTORY                  | I        |                | No              |
| 02/18/2010 | 200231940 | PR         | PR          | SATISFACTORY                  |          |                | No              |
| 12/21/2005 | 200082761 | PR         | SI          | ACTION REQUIRED               |          | Fail           | No              |
| 07/22/2004 | 1230120   | ES         | TA          | ACTION REQUIRED               |          | Fail           | Yes             |
| 10/03/2000 | 896292    | PR         | PR          | ACTION REQUIRED               |          | Fail           | Yes             |
| 12/17/1999 | 894257    | ID         | SI          | ACTION REQUIRED               |          | Fail           | Yes             |
| 05/06/1996 | 500141418 | PR         | PR          |                               |          | Fail           | Yes             |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status                            |
|-------------|------|--------|-------------|------------|-----------|----------------------|--|
| 115183      | PIT  |        | 09/23/1999  |            | -         | CHAMPLIN 569 "E" 2   | <input type="checkbox"/>               |
| 209467      | WELL | PR     | 02/03/2004  | OW         | 039-06372 | CHAMPLIN 569 AMOCO 2 | PR <input checked="" type="checkbox"/> |

**Equipment:****Location Inventory**

Inspector Name: Sherman, Susan

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

### Location

#### Signs/Marker:

| Type     | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY                 |         |                   |         |

Emergency Contact Number (S/A/V): \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

#### Fencing/:

| Type     | Satisfactory/Action Required | Comment     | Corrective Action | CA Date |
|----------|------------------------------|-------------|-------------------|---------|
| WELLHEAD | SATISFACTORY                 | barbed wire |                   |         |

#### Equipment:

| Type                | # | Satisfactory/Action Required | Comment        | Corrective Action | CA Date |
|---------------------|---|------------------------------|----------------|-------------------|---------|
| Deadman # & Marked  | 4 | SATISFACTORY                 |                |                   |         |
| Pump Jack           | 1 | SATISFACTORY                 |                |                   |         |
| Ancillary equipment | 1 | SATISFACTORY                 | electric panel |                   |         |
| Prime Mover         | 1 | SATISFACTORY                 | electric       |                   |         |

#### Facilities:

☐ New Tank

Tank ID: \_\_\_\_\_

| Contents | # | Capacity | Type                | SE GPS |
|----------|---|----------|---------------------|--------|
|          |   |          | CENTRALIZED BATTERY | ,      |

S/A/V: \_\_\_\_\_ Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

#### Paint

Condition \_\_\_\_\_

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

#### Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

Inspector Name: Sherman, Susan

|                   |  |                 |  |
|-------------------|--|-----------------|--|
| Corrective Action |  | Corrective Date |  |
| Comment           |  |                 |  |

|                 |         |
|-----------------|---------|
| <b>Venting:</b> |         |
| Yes/No          | Comment |
|                 |         |

|                 |                              |         |                   |         |
|-----------------|------------------------------|---------|-------------------|---------|
| <b>Flaring:</b> |                              |         |                   |         |
| Type            | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                 |                              |         |                   |         |

**Predrill**

Location ID: 209467

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/A/V:** SATISFACTORY **Comment:** No COAs.

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 209467 Type: WELL API Number: 039-06372 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR. Dec 2014 reported to COGCC database. Submit production data to COGCC.

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: pasture, Bresser sandy loam soil type, good vegetative growth

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM remove orange pail and blue metal beam next to well

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Inspector Name: Sherman, Susan

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

#### Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

#### Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            |                         |                       |               |                          |         |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

S/A/V: SATISFACTOR \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

#### COGCC Comments

| Comment   | User     | Date       |
|---|----------|------------|
| Corrective actions from 3/20/2014, #673701787 inspection completed. | ShermaSe | 05/06/2015 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                      | URL   |
|--------------|----------------------------------|---|
| 673710355    | Renegade Champlin 569<br>Amoco 2 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3604958">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3604958</a> |