

**FORM
INSP**Rev
05/11

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

05/08/2015

Document Number:

674701391

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 334725 | 334725 | LONGWORTH, MIKE | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED
☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|--------------------------------------|-------------------------|
| Inspection, WPX | 970-263-2716 | COGCCInspectionReports@wpxenergy.com | WPX Inspection Mail Box |

Compliance Summary:QtrQtr: NWNW Sec: 5 Twp: 7S Range: 95W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 06/24/2014 | 675100111 | | | SATISFACTORY | | | No |
| 03/19/2014 | 663902847 | | | SATISFACTORY | | | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 262892 | WELL | PR | 07/27/2002 | GW | 045-08069 | PA 311-5 | PR | <input checked="" type="checkbox"/> |
| 262977 | WELL | PR | 08/03/2002 | GW | 045-08086 | PA 21-5 | PR | <input checked="" type="checkbox"/> |
| 286826 | WELL | PR | 03/08/2007 | GW | 045-12795 | PA 22-5 | PR | <input checked="" type="checkbox"/> |
| 286827 | WELL | PR | 12/13/2007 | GW | 045-12794 | PA 322-5 | PR | <input checked="" type="checkbox"/> |
| 286828 | WELL | PR | 09/19/2006 | GW | 045-12793 | PA 422-5 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

Inspector Name: LONGWORTH, MIKE

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |
| CONTAINERS | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: 970-285-9377

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |

Equipment:

| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|---------------------|---|------------------------------|-----------------------------|-------------------|---------|
| Ancillary equipment | 1 | SATISFACTORY | Chemical container at wells | | |
| Plunger Lift | 5 | SATISFACTORY | | | |

Facilities:

☐ New Tank

Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------|---|----------|------|--------|
| | | | | |

S/A/V: _____ Comment: Shared facility w/ loc. ID. 334627

Corrective Action: _____

Corrective Date: _____

Paint

| | |
|-----------|-------|
| Condition | _____ |
|-----------|-------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

Inspector Name: LONGWORTH, MIKE

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
| Comment | | | |

| | |
|-----------------|---------|
| Venting: | |
| Yes/No | Comment |
| | |

| | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 334725

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 262892 Type: WELL API Number: 045-08069 Status: PR Insp. Status: PR

Inspector Name: LONGWORTH, MIKE

Producing Well

Comment: **Producing well**

Facility ID: 262977 Type: WELL API Number: 045-08086 Status: PR Insp. Status: PR

Producing Well

Comment: **Producing well**

Facility ID: 286826 Type: WELL API Number: 045-12795 Status: PR Insp. Status: PR

Producing Well

Comment: **Producing well**

Facility ID: 286827 Type: WELL API Number: 045-12794 Status: PR Insp. Status: PR

Producing Well

Comment: **Producing well**

Facility ID: 286828 Type: WELL API Number: 045-12793 Status: PR Insp. Status: PR

Producing Well

Comment: **Producing well**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Inspector Name: LONGWORTH, MIKE

Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|--|
| Seeding | Pass | | | | | |
| | | Compaction | Pass | | | |
| | | Gravel | Pass | | | |
| | | | | MHSP | Pass | Secondary containment under chemical container |
| Ditches | Pass | | | | | |
| Gravel | Pass | | | | | |

S/A/V: SATISFACTOR

Corrective Date: _____

Y

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT